



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 10,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 HYUNDAI ACCENT

SMART | 73,649 KM

VIN: MALC741C5NM296039

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable

No Flood Damage

No Flood Damage



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	73649	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	16.2 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MALC741C5NM296039		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors						
Fog Light Front			Halogen Headlights			
 Comfort & Convenience						
Cruise Control			Steering Mounted Audio Controls			
Rear Defogger			Central Armrest			
Steering Column Adjuster						



Safety & Security

Parking Sensors Rear



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



USB Charging Port



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm	
-----------------	---	--	---

Rear left door		Rear right door Panel: Light Scuffing < 50mm	
----------------	---	---	---

Fenders Condition

Left Fender Condition: Low Visual Dent		Right Fender	
---	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper Moulding: Fair Use Wear	
---	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE