



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 GEELY MONJARO**

**GK | 24,132 KM**

VIN: LB3KX2S14RS005361

## **Car highlights**



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Bluetooth**

Enjoy your drive with bluetooth

### **Convenience Fee Applicable**
















Extra fee ranging from AED 2.5K-4K applicable



### **Amazing Comfort**












Power driver seat, Memory Seats & more





Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 24132             |  Specs             | Yes                 |
|  Engine           | 2.0L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 8 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys              |
|  VIN number     | LB3KX2S14RS005361 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |  |                                                                                     |                          |  |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------|--------------------------|--|---------------------------------------------------------------------------------------|
| <div> Safety &amp; Security</div> |  |                                                                                     |                          |  |                                                                                       |
| Adaptive cruise control                                                                                              |  |  | 360 degree Camera        |  |  |
| Lane Departure Warning System                                                                                        |  |  | Parking Sensors Front    |  |  |
| Parking Sensors Rear                                                                                                 |  |  | Auto Park Assist         |  |  |
| Reverse Camera                                                                                                       |  |  | Collision Warning System |  |  |
| Traction Control                                                                                                     |  |  | Front Camera             |  |  |

|                                                                                                                    |   |                             |   |
|--------------------------------------------------------------------------------------------------------------------|---|-----------------------------|---|
| Side Camera                                                                                                        | ✓ | Airbag Curtain Shield       | ✓ |
| Airbag Driver Front                                                                                                | ✓ | ABS                         | ✓ |
| Central Locking                                                                                                    | ✓ | Child Safety Locking        | ✓ |
|  <b>Comfort &amp; Convenience</b> |   |                             |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control              | ✓ |
| Memory Seats                                                                                                       | ✓ | Rear Armrest with cupholder | ✓ |
| Steering Mounted Audio Controls                                                                                    | ✓ | Power Folding Mirrors       | ✓ |
| Ventilated Seat                                                                                                    | ✓ | Power Tailgate/ Power Trunk | ✓ |
| Rear Defogger                                                                                                      | ✓ | Central Armrest             | ✓ |
| Remote Engine Start                                                                                                | ✓ | Automatic Headlights        | ✓ |
| Steering Column Adjuster                                                                                           | ✓ |                             |   |
|  <b>Exteriors</b>               |   |                             |   |
| Roof Rails                                                                                                         | ✓ | Running Lights              | ✓ |
| Rear Bumper Spoiler                                                                                                | ✓ | LED Headlights              | ✓ |
|  <b>Performance</b>             |   |                             |   |
| Hill Descent Control                                                                                               | ✓ |                             |   |
|  <b>Entertainment</b>           |   |                             |   |
| Bluetooth Player                                                                                                   | ✓ | USB Charging Port           | ✓ |
| Infotainment System                                                                                                | ✓ | USB player                  | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

|                 |                                                                                   |                              |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door             |  |
|                 |                                                                                   | Panel: Light Scuffing < 50mm |                                                                                     |

|                |                                                                                   |                 |                                                                                     |
|----------------|-----------------------------------------------------------------------------------|-----------------|-------------------------------------------------------------------------------------|
| Rear left door |  | Rear right door |  |
|----------------|-----------------------------------------------------------------------------------|-----------------|-------------------------------------------------------------------------------------|

Fenders Condition

|             |                                                                                   |                                         |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|-----------------------------------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender                            |  |
|             |                                                                                   | Right Fender: Acid Marks/ Bird Dropping |                                                                                     |


Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

Rear Bumper Condition

|                                    |                                                                                     |
|------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |                                                                                     |

Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Roof Condition

|                                                             |                                                                                     |
|-------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Roof                                                        |                                                                                     |
| Roof Moulding Condition: Minor Rubber Beading Fair Use Wear |  |

Pillars Condition

|               |                                                                                     |                |                                                                                       |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|
| Left A Pillar |  | Right A Pillar |  |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|

|                                       |   |                                              |   |
|---------------------------------------|---|----------------------------------------------|---|
| Left A to B Pillar Beading            | ✓ | Right A to B Pillar Beading                  | ✓ |
| Right A to B Pillar                   | ✓ | Left B Pillar                                | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading                   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar                          | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                                | ✓ |
| Running Board Condition               |   |                                              |   |
| Left Running Board                    | ✓ | Right Running Board                          | ! |
|                                       |   | Front Right Sill Trim: Light Scuffing < 80mm |   |
| Sunroof Glass Condition (If Equipped) |   |                                              |   |
| Sun Roof Glass                        | ✓ |                                              |   |
| Windshield Condition                  |   |                                              |   |
| Front Windshield                      | ✓ | Rear Windshield                              | ✓ |
| Structural Assessment                 |   |                                              |   |
| Chassis Condition                     | ✓ | Apron                                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition                           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition                 | ✓ |
| Cowl Top                              |   |                                              |   |
| Cowl Top                              | ✓ |                                              |   |
| Rear View Mirror Condition            |   |                                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror                             | ✓ |
| Right Side Mirror                     | ✓ |                                              |   |
| Alloy Wheel/ Rim                      |   |                                              |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim                         | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim                        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                                              |   |
| Antenna                               | ✓ | Grill Condition                              | ✓ |
| Monogram                              | ✓ | Window Glass                                 | ✓ |
| Wiper                                 | ✓ |                                              |   |

Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Instrument Panel      | ✓ |                         |   |
| Airbags               |   |                         |   |
| Airbags               | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | OBD Connector           | ✓ |
| Radar (If Equipped)   | ✓ | Navigation System       | ✓ |
| Music System          | ✓ |                         |   |
| Sunroof Operation     |   |                         |   |
| Sunroof               | ✓ |                         |   |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| License Plate Light   | ✓ |                         |   |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC Switch               | ✓ |
| AC System Leaks       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent   | ✓ | Heater                  | ✓ |
| Rear Blower Switch    | ✓ |                         |   |
| Rear Defogger         | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows | ✓ | Memory Seats            | ✓ |



## Interiors & Luggage

|                                |   |                                                             |   |
|--------------------------------|---|-------------------------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console<br>Box: Minor Crack/Fair Use Wear/ Scuffing | ⓘ |
| Cup Holder                     | ✓ | Glove Box                                                   | ✓ |



|                        |   |                      |   |
|------------------------|---|----------------------|---|
| Steering Wheel         | ✓ | Sunvisor             | ✓ |
| Seat Upholstery        | ✓ | Manual Seat Movement | ✓ |
| Seat Belts             | ✓ | Head Rest            | ✓ |
| Door Controls And Trim | ✓ | Grab Handle          | ✓ |
| Carpet                 | ✓ | Headliner            | ✓ |
| Rear View Mirror       | ✓ | Toolkit              | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <55% | LHS Rear Tyre             | <65% |
| RHS Front Tyre             | <55% | RHS Rear Tyre             | <85% |
| Spare Tyre                 | <55% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE