

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2021 MITSUBISHI ATTRAGE

GLX HIGHLINE | 76,524 KM

VIN: MMDAFT6J3MH010017

Car highlights

Fuel Efficient

Fuel efficient with 20.2 km/L

Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	76524	Specs	Yes
Engine	1.2L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel Efficiency	20.2 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MMDAFT6J3MH010017		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Exteriors			
Fog Light Front	✓	Rear Bumper Spoiler	✓
Halogen Headlights	✓		
Comfort & Convenience			
Cruise Control	✓	Rear Armrest with cupholder	✓
Steering Mounted Audio Controls	✓	Rear Defogger	✓

Steering Column Adjuster	

Safety & Security	
Traction Control	Airbag Driver Front
ABS	Central Locking
Child Safety Locking	

Entertainment	
Bluetooth Player	USB player

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front left door	✓	Front right door Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm	!
Rear left door	✓	Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	!

Fenders Condition

Left Fender Condition: Dent, Paint Chip-off	!	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel	✓	Right Quarter Panel	✓

Front Bumper Condition

Front Bumper	✓

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	!

Hood Condition

Hood Bonnet: Light Scuffing < 50mm	!

Trunk Condition

Trunk	✓

Trunk conditon

Trunk	✓

Roof Condition

Roof	✓

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Tear In Cover	!
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓

Cowl Top

Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓

Panel Condition

Rear Trunk Panel ✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Fuel System

Fuel Tank ✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering

Steering wheel ✓

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓

Door Locks

Child Safety Locking ✓

Dashboard

Instrument Panel ✓

Airbags

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Fog Lights	✓		

Air Conditioning

AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE