



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 MITSUBISHI ASX

GLX LOW CAMERA +SENSOR | 60,773 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	60773	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JE4LPT1U1MU701646		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	

ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Exteriors			
Running Lights	✓	LED Headlights	✓
 Entertainment			
Bluetooth Player	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Paint Defect	
Rear left door		Rear right door	
		Panel: Paint Defect, Colour Mismatch/ Low Brightness	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	--	---------------------	--

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Crack/ Misaligned, Scuffing > 80mm	

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board Rear Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓

Infotainment Display	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration	!	Grab Handle	✓
Carpet	✓	Headliner Rear Left: Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<45%
RHS Front Tyre	<55%	RHS Rear Tyre	<45%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE