



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 NISSAN MICRA**

**SV | 95,336 KM**

VIN: MDHAK3CR2LG003584

## **Car highlights**

### **Fuel Efficient**

Fuel efficient with 18.8 km/L



### **Amazing Comfort**

Power driver seat

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Airbag safety**

Airbag Driver Front



### **Tilt Steering wheel**

Tilt steering wheel for extra comfort

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 95336             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | HATCHBACK         | Fuel Efficiency                                                                                     | 18.8 km/L mileage    |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | MDHAK3CR2LG003584 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                                     |  |                                                                                                |                          |                                                                                                  |
|-------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------|--------------------------|--------------------------------------------------------------------------------------------------|
| <div></div> <div>Safety &amp; Security</div>     |  |                                                                                                |                          |                                                                                                  |
| Traction Control                                                                                                                    |  | <div></div> | Airbag Driver Front      | <div></div> |
| ABS                                                                                                                                 |  | <div></div> | Central Locking          | <div></div> |
| Child Safety Locking                                                                                                                |  | <div></div> |                          |                                                                                                  |
| <div></div> <div>Comfort &amp; Convenience</div> |  |                                                                                                |                          |                                                                                                  |
| Rear Defogger                                                                                                                       |  | <div></div> | Steering Column Adjuster | <div></div> |



## Exteriors

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                             |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|---------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door                            |  |
|                 |                                                                                   | Panel: Paint Chip-off < 5mm, Low Visibility |                                                                                     |
|                 |                                                                                   | Dent < 30mm, Light Scuffing < 50mm          |                                                                                     |

|                |                                                                                   |                                          |                                                                                     |
|----------------|-----------------------------------------------------------------------------------|------------------------------------------|-------------------------------------------------------------------------------------|
| Rear left door |  | Rear right door                          |  |
|                |                                                                                   | Panel: Light Scuffing < 50mm, Low Visual |                                                                                     |
|                |                                                                                   | Dent < 30mm                              |                                                                                     |

### Fenders Condition

|             |                                                                                   |                                      |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------------------------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender                         |  |
|             |                                                                                   | Right Fender: Low Visual Dent, Light |                                                                                     |
|             |                                                                                   | Scuffing, Paint Chip-off             |                                                                                     |

### Quarter Panels Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                    |                                                                                     |
|------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |                                                                                     |

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                                                |   |                                               |   |
|------------------------------------------------|---|-----------------------------------------------|---|
| Left A Pillar                                  | ✓ | Right A Pillar                                | ✓ |
| Left A to B Pillar Beading                     | ✓ | Right A to B Pillar Beading                   | ✓ |
| Right A to B Pillar                            | ✓ | Left B Pillar                                 | ✓ |
| Left B Pillar Trim                             | ✓ | Left B to C Pillar Beading                    | ✓ |
| Right C Pillar Trim                            | ✓ | Right B to C Pillar                           | ✓ |
| Right B to C Pillar Beading                    | ✓ | Left C Pillar                                 | ✓ |
| Running Board Condition                        |   |                                               |   |
| Left Running Board                             | ✓ | Right Running Board<br>Condition: Dent > 50mm | ! |
| Windshield Condition                           |   |                                               |   |
| Front Windshield                               | ✓ | Rear Windshield                               | ✓ |
| Structural Assessment                          |   |                                               |   |
| Chassis Condition                              | ✓ | Apron                                         | ✓ |
| Boot Floor<br>Condition: Light Scuffing < 80mm | ! | Firewall Condition                            | ✓ |
| Cowl Top                                       | ✓ | Head Light Support Condition                  | ✓ |
| Cowl Top                                       |   |                                               |   |
| Cowl Top                                       | ✓ |                                               |   |
| Rear View Mirror Condition                     |   |                                               |   |
| Left Hand Side Mirror                          | ✓ | Left Side Mirror                              | ✓ |
| Right Side Mirror                              | ✓ |                                               |   |
| Alloy Wheel/ Rim                               |   |                                               |   |
| Left Front Alloy/ Rim                          | ✓ | Left Rear Alloy/ Rim                          | ✓ |
| Right Front Alloy/ Rim                         | ✓ | Right Rear Alloy/ Rim                         | ✓ |
| Spare Alloy/ Rim Condition                     | ✓ |                                               |   |
| Wheel cover                                    | ✓ | Antenna                                       | ✓ |
| Grill Condition<br>Light Scuffing < 50mm       | ! | Monogram                                      | ✓ |
| Window Glass                                   | ✓ | Wiper                                         | ✓ |

Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                       |   |                     |   |
|-----------------------|---|---------------------|---|
| Airbags               | ✓ |                     |   |
| Controls              | ✓ | Cruise Control      | ✓ |
| Infotainment Display  | ✓ | OBD Connector       | ✓ |
| Music System          | ✓ |                     |   |
| Lights                |   |                     |   |
| Headlight             | ✓ | Interior Lights     | ✓ |
| Tail Light Cluster    | ✓ | License Plate Light | ✓ |
| Air Conditioning      |   |                     |   |
| AC Cooling            | ✓ | AC Switch           | ✓ |
| AC System Leaks       | ✓ | Center AC Vent      | ✓ |
| Front Right AC Vent   | ✓ | Heater              | ✓ |
| Power/ Manual Windows | ✓ |                     |   |

## Interiors & Luggage

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Glove Box                      | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Grab Handle                    | ✓ | Carpet                 | ✓ |
| Headliner                      | ✓ | Rear View Mirror       | ✓ |
| Toolkit                        | ✓ |                        |   |

## Tyres

Tyres Condition

|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Left Hand Side Front Tyre  |   | Left Hand Side Rear Tyre  |   |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                     |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <65%                                                                              | LHS Rear Tyre             | <75%                                                                                |
| RHS Front Tyre             | <65%                                                                              | RHS Rear Tyre             | <65%                                                                                |
| Spare Tyre                 | <75%                                                                              |                           |                                                                                     |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE