



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2022 HYUNDAI ACCENT SMART | 98,580 KM

# **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



## **Great Parking Assistance**

Parking Sensors Rear

## **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



#### **Bluetooth**


Enjoy your drive with bluetooth



### **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Safety & Security			
Parking Sensors Rear	~	Traction Control	•
Airbag Driver Front	<b>✓</b>	ABS	<b>✓</b>
Central Locking	<b>✓</b>	Child Safety Locking	<b>✓</b>
<b>□</b> s Entertainment			
Bluetooth Player	~	USB Charging Port	•
USB player	<b>✓</b>		


## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Windshield Condition Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	•
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>✓</b>
Boot Floor	<b>~</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>✓</b>
Cowl Top			
Cowl Top	<b>~</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	~		
Wheel cover	•	Antenna	<b>✓</b>
Grill Condition Light Scuffing < 50mm	!	Monogram	<b>✓</b>
Window Glass	•	Wiper	•

Panel Condition			
Rear Trunk Panel	<b>✓</b>		
Engine & Transmission			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>
Transmission Fluid	<b>✓</b>		
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>		
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			



Front Left: Light Smudge/Disfiguration

Toolkit



# Tyres

Tyres	Condition
-------	-----------

Left Hand Side Front Tyre Left Hand Side Rear Tyre

Right Hand Side Front Tyre Right Hand Side Rear Tyre

Spare Tyre

Life remaining

LHS Front Tyre <45% LHS Rear Tyre <55%

RHS Front Tyre <45% RHS Rear Tyre <55%

Spare Tyre <65%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE