



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 FORD EDGE

TITANIUM | 107,896 KM

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play
















Enjoy your drive with apple play



Amazing Comfort












Power driver seat, Memory Seats & more





Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 107896 |  Specs | Yes |
|  Engine | 3.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Leather Trim |  Number of Airbags | 8 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | 2FMPK4K85HBB24497 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-----------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Memory Seats |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls |  | Ventilated Seat |  |
| Power Tailgate/ Power Trunk |  | Rear Defogger |  |
| Central Armrest |  | Remote Engine Start |  |

| | | |
|---|---|------------------------|
| Steering Column Adjuster | ✓ | |
| <div>  Performance </div> | | |
| Paddle Shift | ✓ | |
| <div>  Safety & Security </div> | | |
| Parking Sensors Rear | ✓ | Reverse Camera ✓ |
| Blind Spot Monitor | ✓ | Traction Control ✓ |
| Airbag Curtain Shield | ✓ | Airbag Knees ✓ |
| Airbag Driver Front | ✓ | ABS ✓ |
| Central Locking | ✓ | Child Safety Locking ✓ |
| <div>  Exteriors </div> | | |
| Running Lights | ✓ | Rear Bumper Spoiler ✓ |
| Halogen Headlights | ✓ | |
| <div>  Entertainment </div> | | |
| Bluetooth Player | ✓ | Apple Play ✓ |
| Android Auto Play | ✓ | Infotainment System ✓ |
| USB player | ✓ | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|---|---|
| Front left door |  | Front right door Panel: Low Visibility Dent < 30mm, Paint Chip-off < 5mm |  |
|-----------------|---|---|---|

| | | | |
|----------------|---|--|---|
| Rear left door |  | Rear right door Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm |  |
|----------------|---|--|---|

Fenders Condition

| | | | |
|---|---|--|---|
| Left Fender Condition: Low Visual Dent, Paint Chip-off |  | Right Fender Right Fender: Light Scuffing |  |
|---|---|--|---|


Quarter Panels Condition

| | | | |
|--------------------|---|---|---|
| Left Quarter Panel |  | Right Quarter Panel Condition: Low Visual Dent |  |
|--------------------|---|---|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper Rear Bumper: Light Scuffing < 80mm |  |
|---|---|

Hood Condition

| | |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|---------------------------------------|---|------------------------------|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | | | |
| Body: Paint Defects | ! | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |

| | | |
|------------------|---|--|
| Wiper | ✓ | |
| Panel Condition | | |
| Rear Trunk Panel | ✓ | |

Engine & Transmission

| | | |
|--------------------------------|---|----------------------|
| Engine | | |
| Engine Body | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓ |
| Radiator Condition | ✓ | Radiator Coolant ✓ |
| Fuel System | | |
| Fuel Tank | ✓ | |
| Transmission Operation | | |
| Gear Shifting | ✓ | Gear shift ✓ |
| Drive Axle | ✓ | Transmission Fluid ✓ |

Steering, Suspension & Brakes

| | | |
|------------------------|---|-------------------------|
| Steering | | |
| Steering wheel | ✓ | |
| Brake System | | |
| Parking Brake | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓ |
| Suspension | | |
| Shock Absorbers | ✓ | |

Electricals, Controls & Lights

| | | |
|----------------------|---|--|
| Keys | | |
| Master Key | ✓ | |
| Door Locks | | |
| Child Safety Locking | ✓ | |
| Dashboard | | |

| | | | |
|-----------------------|---|-------------------------|---|
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | Memory Seats | ✓ |



Interiors & Luggage

| | | | |
|--|---|-----------------|---|
| Dashboard And Instrument Panel | | | |
| Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted | ! | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |

| | | | |
|------------------------|---|----------------------|---|
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE