



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 TOYOTA RUSH

EX | 75,606 KM

## Car highlights



### **Great Parking Assistance**

Parking Sensors Rear

### **LED headlamp**

This car has a LED headlamp

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 75606             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Rear Wheel Drive     |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 12.9 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 8 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | MHKEF8BF9PK035922 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Steering Mounted Audio Controls |  |
| Rear Defogger                                                                                                        |  | Steering Column Adjuster        |  |
|  <b>Exteriors</b>                 |                                                                                     |                                 |                                                                                       |
| Fog Light Front                                                                                                      |  | Roof Rails                      |  |
| Rear Bumper Spoiler                                                                                                  |  | LED Headlights                  |  |



## Safety & Security

Parking Sensors Rear



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

|                 |                                                                                   |                              |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door             |  |
| Rear left door  |  | Rear right door              |  |
|                 |                                                                                   | Panel: Light Scuffing < 50mm |                                                                                     |

Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

Pillars Condition

|                            |                                                                                     |                             |                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
| Right A to B Pillar        |  | Left B Pillar               |  |

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   |                              |   |
| Light Scuffing < 50mm       | ! | Monogram                     | ✓ |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |

## Engine & Transmission

Engine

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |

## Electricals, Controls & Lights

|                      |   |                      |   |
|----------------------|---|----------------------|---|
| Keys                 |   |                      |   |
| Master Key           | ✓ | Spare Key(s)         | ✓ |
| Door Locks           |   |                      |   |
| Child Safety Locking | ✓ |                      |   |
| Dashboard            |   |                      |   |
| Instrument Panel     | ✓ |                      |   |
| Airbags              |   |                      |   |
| Airbags              | ✓ |                      |   |
| Controls             | ✓ | Cruise Control       | ✓ |
| Heads Up Display     | ✓ | Infotainment Display | ✓ |

|                       |   |                     |   |
|-----------------------|---|---------------------|---|
| OBD Connector         | ✓ | Music System        | ✓ |
| Lights                |   |                     |   |
| Headlight             | ✓ | Interior Lights     | ✓ |
| Tail Light Cluster    | ✓ | License Plate Light | ✓ |
| Fog Lights            | ✓ |                     |   |
| Air Conditioning      |   |                     |   |
| AC Cooling            | ✓ | AC Switch           | ✓ |
| AC System Leaks       | ✓ | Center AC Vent      | ✓ |
| Front Right AC Vent   | ✓ | Heater              | ✓ |
| Rear Blower Switch    |   |                     |   |
| Crack                 | ! | Rear Left AC Vent   | ✓ |
| Parking Sensors       | ✓ | USB Charging Port   | ✓ |
| Power/ Manual Windows | ✓ | Memory Seats        | ✓ |



## Interiors & Luggage

|                                          |   |                                       |   |
|------------------------------------------|---|---------------------------------------|---|
| Dashboard And Instrument Panel           | ✓ | Central Console                       | ✓ |
| Cup Holder                               | ✓ | Glove Box                             | ✓ |
| Steering Wheel                           | ✓ | Sunvisor                              | ! |
|                                          |   | Left: Sunvisor RHS Minor Crack/Damage |   |
| Seat Upholstery                          |   |                                       |   |
| Rear Left Seat: Leather/ Fabric Fair Use | ! | Manual Seat Movement                  | ✓ |
| Wear/ Tears                              |   |                                       |   |
| Seat Belts                               | ✓ | Head Rest                             | ✓ |
| Door Controls And Trim                   |   |                                       |   |
| Front Left Door: Scuffing/ Disfiguration | ! | Grab Handle                           | ✓ |
| Carpet                                   | ✓ | Headliner                             | ✓ |
| Rear View Mirror                         | ✓ | Toolkit                               | ✓ |



## Tyres



|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Tyres Condition            |                                                                                   |                           |                                                                                     |
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                     |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <55%                                                                              | LHS Rear Tyre             | <65%                                                                                |
| RHS Front Tyre             | <65%                                                                              | RHS Rear Tyre             | <55%                                                                                |
| Spare Tyre                 | <65%                                                                              |                           |                                                                                     |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE