



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 CHEVROLET GROOVE

PREMIER | 101,845 KM

VIN: LZWADAGA3PG019217

## Car highlights



### Panoramic Roof

This car has a panoramic roof



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>101845</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel Efficiency	<b>16.4 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>4 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>LZWADAGA3PG019217</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Steering Mounted Audio Controls	
Rear Defogger	
Steering Column Adjuster	
 <b>Safety &amp; Security</b>	

Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			

 **Exteriors**

Roof Rails		Running Lights	
LED Headlights			

 **Entertainment**

Bluetooth Player		Apple Play	
Android Auto Play		USB Charging Port	
Infotainment System		USB player	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Handle: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender

Condition: Low Visual Dent, Light Scuffing,



Right Fender



Paint Chip-off

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Acid Marks/



Bird Dropping < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Roof Moulding Condition: Colour fade

#### Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

#### Running Board Condition

Left Running Board		Right Running Board	
--------------------	--	---------------------	--

#### Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

#### Windshield Condition

##### Front Windshield

Condition: Driver Side/Stone Chip		
Mark<5mm, Passenger Side/Stone Chip		Rear Windshield
Mark<8mm		

#### Structural Assessment

Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			

#### Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			

#### Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			

Antenna		Grill Condition	
Monogram		Light Scuffing < 50mm	
Wiper		Window Glass	
Operation: Cover Missing			
Panel Condition			
Rear Trunk Panel			

---

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Fuel System			
Fuel Tank			
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

---

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Suspension			
Shock Absorbers			

---

## Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
Door Locks	✓		
Child Safety Locking	✓		
Dashboard	✓		
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

## **Interiors & Luggage**

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/  
Disfigurement/ Melted, Minor Scuffing/ Crack/



### Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



		Glove Box	
Cup Holder	✓	Glove Box: Minor Scuffing/Crack/Fair Use Wear	!
Steering Wheel	!	Sunvisor	
Color Faded		Left: Sunvisor RHS Vanity Mirror Cover Damage	!
Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks		Head Rest	✓
Seat Belts	✓	Grab Handle	✓
Door Controls And Trim	✓	Headliner	✓
Carpet		Toolkit	✓
Front Left Floor Mat: Smudge/Burn/Crack	!		
Rear View Mirror	✓		

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<45%	LHS Rear Tyre	<55%
RHS Front Tyre	<45%	RHS Rear Tyre	<55%
Spare Tyre	<85%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE