



### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2023 NISSAN ALTIMA S | 24,249 KM

VIN: 1N4BL4A95PN405987

## **Car highlights**



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Bluetooth**


Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Parking Sensors Rear	<b>~</b>	Traction Control	<b>~</b>
Airbag Driver Front	<b>✓</b>	ABS	<b>✓</b>
Central Locking	<b>✓</b>	Child Safety Locking	<b>✓</b>
Exteriors			
Running Lights	~	LED Headlights	<b>✓</b>
<b>□</b> Entertainment			
Bluetooth Player	~	USB Charging Port	<b>✓</b>
Infotainment System	<b>✓</b>	USB player	<b>✓</b>


## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>✓</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>✓</b>
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	<b>✓</b>		
Grill Condition	<b>✓</b>	Monogram	<b>✓</b>
Window Glass	<b>✓</b>	Wiper	•
Panel Condition			
Rear Trunk Panel	<b>✓</b>		
Engine & Transmission			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Fuel System			





RHS Front Tyre <65% RHS Rear Tyre <65%

Spare Tyre <75%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE