



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2022 NISSAN X TRAIL S | 55,603 KM

# Car highlights



#### **Great condition**

Car has low imperfections



#### **Cruise control**

Cruise control to drive with ease & comfort

## **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



#### **Bluetooth**

Enjoy your drive with bluetooth



## **Amazing Comfort**


Power driver seat


### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.





## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>✓</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>✓</b>
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel cover	<b>✓</b>	Antenna	•
Grill Condition	•	Monogram	•
Window Glass	<b>✓</b>	Wiper	<b>✓</b>
Panel Condition			
Rear Trunk Panel	<b>✓</b>		

Engine & Transmission			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>
Transmission Fluid	<b>✓</b>		
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>		
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		

Controls	<b>✓</b>	Cruise Control	<b>✓</b>
Infotainment Display	<b>✓</b>	OBD Connector	<b>✓</b>
Music System	<b>✓</b>		
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Daylight Running Lights	<b>✓</b>
License Plate Light	<b>✓</b>		
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>~</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	<b>✓</b>
Rear Blower Switch	<b>✓</b>		
USB Charging Port	<b>✓</b>	Power/ Manual Windows	<b>✓</b>
Memory Seats	<b>✓</b>		
Memory Seats  All Interiors & Luggage	<b>✓</b>		
	<ul><li></li><li></li></ul>	Central Console	<b>✓</b>
🖺 Interiors & Luggage	<ul><li></li><li></li><li></li></ul>	Central Console  Glove Box	*
Interiors & Luggage  Dashboard And Instrument Panel	<ul><li></li><li></li><li></li><li></li><!--</td--><td></td><td><ul><li>✓</li><li>✓</li><li>✓</li></ul></td></ul>		<ul><li>✓</li><li>✓</li><li>✓</li></ul>
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder	<ul><li>*</li><li>*</li><li>*</li><li>*</li></ul>	Glove Box	<ul><li>*</li><li>*</li><li>*</li></ul>
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel	<ul><li>*</li><li>*</li><li>*</li><li>*</li><li>*</li></ul>	Glove Box Sunvisor	
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery		Glove Box Sunvisor Manual Seat Movement	
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery  Seat Belts		Glove Box Sunvisor Manual Seat Movement Head Rest	
Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery  Seat Belts  Door Controls And Trim		Glove Box  Sunvisor  Manual Seat Movement  Head Rest  Grab Handle	

### Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Life remaining LHS Front Tyre <75% LHS Rear Tyre <85% RHS Front Tyre <75% RHS Rear Tyre <85% Spare Tyre <75%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE