



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2021 MAZDA 6**

**S | 66,826 KM**

VIN: JM7GL4S33M1457038

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 66826             |  Specs             | Yes                 |
|  Engine           | 2.5L              |  Option Type       | Basic               |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 12.8 km/L mileage   |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 6 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys              |
|  VIN number     | JM7GL4S33M1457038 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                  |  |
| Rear Armrest with cupholder                                                                                          |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors                                                                                                |  | Rear Defogger                   |  |
| Central Armrest                                                                                                      |  | Steering Column Adjuster        |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                 |                                                                                       |

|                                                                                                        |   |                       |   |
|--------------------------------------------------------------------------------------------------------|---|-----------------------|---|
| Parking Sensors Rear                                                                                   | ✓ | Reverse Camera        | ✓ |
| Traction Control                                                                                       | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front                                                                                    | ✓ | ABS                   | ✓ |
| Central Locking                                                                                        | ✓ | Child Safety Locking  | ✓ |
|  <b>Exteriors</b>     |   |                       |   |
| Running Lights                                                                                         | ✓ | LED Headlights        | ✓ |
|  <b>Entertainment</b> |   |                       |   |
| Bluetooth Player                                                                                       | ✓ | USB player            | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                              |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door             |  |
|                 |                                                                                   | Handle: Paint Chip-off < 5mm |                                                                                     |

|                |                                                                                   |                                                                             |                                                                                     |
|----------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear left door |  | Rear right door                                                             |  |
|                |                                                                                   | Panel: Paint Defect, Colour Mismatch/ Low Brightness, Light Scuffing < 50mm |                                                                                     |

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                     |                                                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------|---------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel                                 |  |
|                    |                                                                                     | Condition: Acid Marks/Bird Dropping, Light Scuffing |                                                                                       |

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                    |                                                                                     |
|------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |                                                                                     |

### Hood Condition

|                                      |                                                                                     |
|--------------------------------------|-------------------------------------------------------------------------------------|
| Hood                                 |  |
| Bonnet: Paint Damage/ Low Brightness |                                                                                     |

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left A Pillar               | ✓ | Right A Pillar               | ✓ |
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   | Monogram                     | ✓ |
| Colour Faded                | ! |                              |   |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |

|                  |   |
|------------------|---|
| Rear Trunk Panel | ✓ |
|------------------|---|

## Engine & Transmission

### Engine

|             |   |                    |   |
|-------------|---|--------------------|---|
| Engine Body | ✓ | Engine Performance | ✓ |
|-------------|---|--------------------|---|

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
|--------------------------------|---|----------------|---|

|                    |   |                  |   |
|--------------------|---|------------------|---|
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
|--------------------|---|------------------|---|

### Fuel System

|           |   |
|-----------|---|
| Fuel Tank | ✓ |
|-----------|---|

### Transmission Operation

|               |   |            |   |
|---------------|---|------------|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |
|---------------|---|------------|---|

|                    |   |
|--------------------|---|
| Transmission Fluid | ✓ |
|--------------------|---|

## Steering, Suspension & Brakes

### Steering

|                |   |
|----------------|---|
| Steering wheel | ✓ |
|----------------|---|

### Brake System

|               |   |                       |   |
|---------------|---|-----------------------|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
|---------------|---|-----------------------|---|

|                        |   |             |   |
|------------------------|---|-------------|---|
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
|------------------------|---|-------------|---|

### Suspension

|                 |   |
|-----------------|---|
| Shock Absorbers | ✓ |
|-----------------|---|

## Electricals, Controls & Lights

### Keys

|                          |   |
|--------------------------|---|
| Master Key               | ⚠ |
| Manual Key Not Available |   |

### Door Locks

|                      |   |
|----------------------|---|
| Child Safety Locking | ✓ |
|----------------------|---|

### Dashboard

|                  |   |
|------------------|---|
| Instrument Panel | ✓ |
|------------------|---|

### Airbags

|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Airbags              | ✓ |                         |   |
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | OBD Connector           | ✓ |
| Music System         | ✓ | Camera                  | ✓ |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| License Plate Light  | ✓ |                         |   |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC Switch               | ✓ |
| AC System Leaks      | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent  | ✓ | Heater                  | ✓ |
| Rear Blower Switch   | ✓ |                         |   |
| Parking Sensors      | ✓ | Rear Defogger           | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows   | ✓ |

## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/  
Fair Use Wear, Minor Scuffing/ Disfiguration/  
Melted



Central Console



Cup Holder



Glove Box



Steering Wheel

Color Faded



Sunvisor



Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use  
Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest



|                        |   |                                 |   |
|------------------------|---|---------------------------------|---|
| Door Controls And Trim | ✓ | Grab Handle                     | ✓ |
| Carpet                 | ✓ | Headliner                       | ! |
|                        |   | Rear Left: Smudge/Disfiguration |   |
| Rear View Mirror       | ✓ | Toolkit                         | ✓ |

## Tyres

### Tyres Condition

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <65% | LHS Rear Tyre             | <55% |
| RHS Front Tyre             | <65% | RHS Rear Tyre             | <85% |
| Spare Tyre                 | <45% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE