



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 KIA PICANTO

LX | 46,390 KM

## Car highlights



### Great condition

Car has low imperfections



### Great Parking Assistance

Reverse Camera

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play















Enjoy your drive with apple play



### Amazing Comfort











Power driver seat

Basic Details

|  |                   |   |                     |
|--|-------------------|---|---------------------|
|  Kilometers       | 46390             |  Specs             | Yes                 |
|  Engine           | 1.2L              |  Option Type       | Basic               |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | HATCHBACK         | Fuel Efficiency   | 17.6 km/L mileage   |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color Gold |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys              |
|  VIN number     | KNAB25120PT115820 |   |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |  |   |                      |   |
|--|--|---|----------------------|---|
|  <b>Safety &amp; Security</b>     |  |   |                      |   |
| Reverse Camera   |  |  | Traction Control     |  |
| Airbag Driver Front  |  |  | ABS                  |  |
| Central Locking  |  |  | Child Safety Locking |  |
|  <b>Comfort &amp; Convenience</b> |  |   |                      |   |
| Steering Mounted Audio Controls  |  |  | Rear Defogger        |  |

Steering Column Adjuster



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



Infotainment System



USB player



Exteriors

Halogen Headlights



















# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|   |   |   |   |
|---|---|---|---|
| Doors condition                                   |   |   |   |
| Front left door                                   |    | Front right door  |    |
| Rear left door                                    |    | Rear right door<br>Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm |    |
| Fenders Condition                                 |   |   |   |
| Left Fender                                       |    | Right Fender<br>Right Fender: Paint Chip-off                            |    |
| Quarter Panels Condition                          |   |   |   |
| Left Quarter Panel                                |   | Right Quarter Panel   |   |
| Front Bumper Condition                            |   |   |   |
| Front Bumper                                      |  |   |   |
| Rear Bumper Condition                             |   |   |   |
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm |  |   |   |
| Hood Condition                                    |   |   |   |
| Hood  |  |   |   |
| Trunk Condition                                   |   |   |   |
| Trunk   |  |   |   |
| Trunk conditon                                    |   |   |   |
| Trunk   |  |   |   |
| Roof Condition                                    |   |   |   |
| Roof  |  |   |   |
| Pillars Condition                                 |   |   |   |
| Left A Pillar                                     |  | Right A Pillar  |  |

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   | Monogram                     | ✓ |
| Light Scuffing < 50mm       | ! |                              |   |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



|                     |   |                       |   |
|---------------------|---|-----------------------|---|
| Controls            | ✓ | Infotainment Display  | ✓ |
| OBD Connector       | ✓ | Music System          | ✓ |
| Camera              | ✓ |                       |   |
| Lights              |   |                       |   |
| Headlight           | ✓ | Interior Lights       | ✓ |
| Tail Light Cluster  | ✓ | License Plate Light   | ✓ |
| Air Conditioning    |   |                       |   |
| AC Cooling          | ✓ | AC Switch             | ✓ |
| AC System Leaks     | ✓ | Center AC Vent        | ✓ |
| Front Right AC Vent | ✓ | Heater                | ✓ |
| USB Charging Port   | ✓ | Power/ Manual Windows | ✓ |




## Interiors & Luggage

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Glove Box                      | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Grab Handle                    | ✓ | Carpet                 | ✓ |
| Headliner                      | ✓ | Rear View Mirror       | ✓ |
| Toolkit                        | ✓ |                        |   |

## Tyres

|                           |   |                          |   |
|---------------------------|---|--------------------------|---|
| Tyres Condition           |   |                          |   |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |



|                            |   |                           |  |
|----------------------------|---|---------------------------|--|
| Right Hand Side Front Tyre |   | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |  |
| Life remaining             |   |                           |  |
| LHS Front Tyre             | <65%  | LHS Rear Tyre             | <65%   |
| RHS Front Tyre             | <55%  | RHS Rear Tyre             | <65%   |
| Spare Tyre                 | <45%  |                           |  |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE