



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 NISSAN SUNNY

S | 63,496 KM

Car highlights



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|----------------------------|
|  Kilometers | 63496 |  Specs | Yes |
|  Engine | 1.5L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel Efficiency | 15.4 km/L mileage |
|  Wheel Type | Steel Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | MDHBN7AD7NG147628 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience | |
|--|---|
| Rear Armrest with cupholder |  |
| Steering Column Adjuster |  |
|  Safety & Security | |
| Parking Sensors Rear |  |
| Traction Control |  |
| Rear Defogger |  |
| Reverse Camera |  |
| Airbag Driver Front |  |

| | | | |
|----------------------|---|---------------------|---|
| ABS |  | Central Locking |  |
| Child Safety Locking |  | | |
| Entertainment | | | |
| Bluetooth Player |  | Infotainment System |  |
| USB player |  | | |
| Exteriors | | | |
| Halogen Headlights |  | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Paint



Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

| | | | |
|-----------------------------|--|------------------------------|--|
| Left A Pillar | | Right A Pillar | |
| Left A to B Pillar Beading | | Right A to B Pillar Beading | |
| Right A to B Pillar | | Left B Pillar | |
| Left B Pillar Trim | | Left B to C Pillar Beading | |
| Right C Pillar Trim | | Right B to C Pillar | |
| Right B to C Pillar Beading | | Left C Pillar | |
| Running Board Condition | | | |
| Left Running Board | | Right Running Board | |
| Windshield Condition | | | |
| Front Windshield | | Rear Windshield | |
| Structural Assessment | | | |
| Chassis Condition | | Apron | |
| Boot Floor | | Firewall Condition | |
| Cowl Top | | Head Light Support Condition | |
| Cowl Top | | | |
| Cowl Top | | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | | Left Side Mirror | |
| Right Side Mirror | | | |
| Alloy Wheel/ Rim | | | |
| Spare Alloy/ Rim Condition | | | |
| Wheel cover | | Antenna | |
| Grill Condition | | Monogram | |
| Window Glass | | Wiper | |
| Panel Condition | | | |
| Rear Trunk Panel | | | |

Engine & Transmission

Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

Fuel System

Fuel Tank 

Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Suspension

Shock Absorbers 

Electricals, Controls & Lights

Keys

Master Key  Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls  Cruise Control 

| | | | |
|----------------------|---|-----------------------|---|
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | Camera | ✓ |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | License Plate Light | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|---------------------------|---|--------------------------|---|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |

Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<45%

LHS Rear Tyre

<55%

RHS Front Tyre

<45%

RHS Rear Tyre

<55%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE