



### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



### **2022 NISSAN KICKS**

S | 27,311 KM

VIN: 3N1CP5C94NL464986

# **Car highlights**



### **Low Mileage**

This car has been driven less than 15,000 km a year



#### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



#### **Bluetooth**


Enjoy your drive with bluetooth



### **Amazing Comfort**


Power driver seat


### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.






## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Windshield Condition			
Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	(!)	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>✓</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>✓</b>
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>~</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel cover	~	Antenna	<b>✓</b>
Grill Condition Light Scuffing < 50mm	!	Monogram	<b>✓</b>
		MC	
Window Glass	<b>✓</b>	Wiper	•
Panel Condition			

Rear Trunk Panel	•					
Engine & Transmission						
Engine						
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>			
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>			
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>			
Fuel System						
Fuel Tank	<b>✓</b>					
Transmission Operation						
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>			
Transmission Fluid	<b>✓</b>					
Steering, Suspension & Brakes						
Steering						
Steering wheel	<b>✓</b>					
Brake System						
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>			
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>			
Suspension						
Shock Absorbers	<b>✓</b>					
Electricals, Controls & Lights						
Keys						
Master Key	<b>✓</b>	Spare Key(s)	<b>✓</b>			
Door Locks						
Child Safety Locking	<b>✓</b>					
Dashboard						
Instrument Panel	<b>✓</b>					
Airbags						



Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	<b>✓</b>	Right Hand Side Rear Tyre	<b>✓</b>
Spare Tyre	<b>✓</b>		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<85%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE