



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 NISSAN KICKS**

**S | 68,518 KM**

VIN: 3N1CP5C97NL472144

## **Car highlights**



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                       |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers       | 68518             |  Specs             | Yes                   |
|  Engine           | 1.6L              |  Option Type       | Basic                 |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive     |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 15.4 km/L mileage     |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Silver |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags             |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys                |
|  VIN number     | 3N1CP5C97NL472144 |                                                                                                     |                       |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                 |                                                                                       |
| Cruise Control                                                                                                       |  | Steering Mounted Audio Controls |  |
| Rear Defogger                                                                                                        |  | Central Armrest                 |  |
| Steering Column Adjuster                                                                                             |  |                                 |                                                                                       |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                 |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Reverse Camera                  |  |

|                                                                                                        |   |                     |   |
|--------------------------------------------------------------------------------------------------------|---|---------------------|---|
| Traction Control                                                                                       | ✓ | Airbag Driver Front | ✓ |
| ABS                                                                                                    | ✓ | Central Locking     | ✓ |
| Child Safety Locking                                                                                   | ✓ |                     |   |
|  <b>Exteriors</b>     |   |                     |   |
| Roof Rails                                                                                             | ✓ | Halogen Headlights  | ✓ |
|  <b>Entertainment</b> |   |                     |   |
| Bluetooth Player                                                                                       | ✓ | Infotainment System | ✓ |
| USB player                                                                                             | ✓ |                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender

Right Fender: Light Scuffing



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



|                                               |   |                              |   |
|-----------------------------------------------|---|------------------------------|---|
| Right A to B Pillar                           | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                            | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                           | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading                   | ✓ | Left C Pillar                | ✓ |
| Running Board Condition                       |   |                              |   |
| Left Running Board                            | ✓ | Right Running Board          | ✓ |
| Windshield Condition                          |   |                              |   |
| Front Windshield                              |   |                              |   |
| Condition: Passenger Side/Stone Chip Mark<8mm | ! | Rear Windshield              | ✓ |
| Structural Assessment                         |   |                              |   |
| Chassis Condition                             | ✓ | Apron                        | ✓ |
| Boot Floor                                    | ✓ | Firewall Condition           | ✓ |
| Cowl Top                                      | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                                      |   |                              |   |
| Cowl Top                                      | ✓ |                              |   |
| Rear View Mirror Condition                    |   |                              |   |
| Left Hand Side Mirror                         | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                             | ✓ |                              |   |
| Alloy Wheel/ Rim                              |   |                              |   |
| Left Front Alloy/ Rim                         | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                        | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition                    | ✓ |                              |   |
| Wheel cover                                   | ✓ | Antenna                      | ✓ |
| Grill Condition                               |   |                              |   |
| Light Scuffing < 50mm                         | ! | Monogram                     | ✓ |
| Window Glass                                  | ✓ | Wiper                        | ✓ |
| Panel Condition                               |   |                              |   |
| Rear Trunk Panel                              | ✓ |                              |   |

## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | OBD Connector           | ✓ |
| Music System         | ✓ | Camera                  | ✓ |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| License Plate Light  | ✓ |                         |   |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC Switch               | ✓ |
| AC System Leaks      | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent  | ✓ | Heater                  | ✓ |
| Parking Sensors      | ✓ | Rear Defogger           | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows   | ✓ |



## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle          | ✓ |
| Carpet                         | ✓ | Headliner            | ✓ |
| Rear View Mirror               | ✓ | Toolkit              | ✓ |



## Tyres

|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Tyres Condition            |                                                                                   |                           |                                                                                     |
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                     |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <65%                                                                              | LHS Rear Tyre             | <55%                                                                                |
| RHS Front Tyre             | <65%                                                                              | RHS Rear Tyre             | <65%                                                                                |
| Spare Tyre                 | <85%                                                                              |                           |                                                                                     |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE