



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2025 GEELY EMGRAND**

**GS | 18,901 KM**

VIN: LB3F31S31SG007411

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**















Enjoy your drive with apple play



### **Amazing Comfort**










Power driver seat



## Basic Details

 Kilometers	<b>18901</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	Fuel Efficiency	<b>10.8 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>LB3F31S31SG007411</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Remote Engine Start	
Steering Column Adjuster			
 <b>Safety &amp; Security</b>			

Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 <b>Exteriors</b>			
Running Lights		LED Headlights	
 <b>Entertainment</b>			
Bluetooth Player		Apple Play	
Android Auto Play		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door  Front right door 

Rear left door  Rear right door 

### Fenders Condition

Left Fender  Right Fender 

### Quarter Panels Condition

Left Quarter Panel  Right Quarter Panel   
Condition: Low Visual Dent

### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper   
Rear Bumper: Light Scuffing < 80mm

### Hood Condition

Hood   
Bonnet: Low Visibility Dent < 30mm

### Trunk Condition

Trunk 

### Trunk condition

Trunk 

### Roof Condition

Roof 

### Pillars Condition

Left A Pillar  Right A Pillar 

Left A to B Pillar Beading  Right A to B Pillar Beading 

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

---

## **Steering, Suspension & Brakes**

### Steering

Steering wheel ✓

### Brake System

Parking Brake ✓ Brake Master Cylinder ✓

Brake Disc & Brake Pad ✓ Brake Fluid ✓

### Suspension

Shock Absorbers ✓

---

## **Electricals, Controls & Lights**

### Keys

Master Key ✓ Spare Key(s) ✓

### Door Locks

Child Safety Locking ✓

### Dashboard

Instrument Panel ✓

### Airbags

Airbags ✓

Controls ✓ Cruise Control ✓

Infotainment Display	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

### Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

## Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



## Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<65%

RHS Front Tyre

<55%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE