



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2021 TOYOTA YARIS SE | 88,526 KM

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.






150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



| Left B Pillar Trim Left B to C Pillar Beading Right C Pillar Trim Right B to C Pillar | |
|--|--|
| Right C Pillar Trim Right B to C Pillar | |
| | |
| Right B to C Pillar Beading Left C Pillar | |
| Running Board Condition | |
| Left Running Board Right Running Board | |
| Windshield Condition | |
| Front Windshield Rear Windshield | |
| Structural Assessment | |
| Chassis Condition | |
| Boot Floor Firewall Condition | |
| Cowl Top Head Light Support Condition | |
| Cowl Top | |
| Cowl Top | |
| Rear View Mirror Condition | |
| Left Hand Side Mirror Left Side Mirror | |
| Right Side Mirror | |
| Alloy Wheel/ Rim | |
| Left Front Alloy/ Rim ✓ Left Rear Alloy/ Rim | |
| Right Front Alloy/ Rim Right Rear Alloy/ Rim | |
| Spare Alloy/ Rim Condition | |
| Wheel cover Antenna | |
| Grill Condition Monogram | |
| Window Glass Wiper | |
| Panel Condition | |
| Rear Trunk Panel | |

| Liigiile | | | |
|--------------------------------|----------|-----------------------|----------|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Gear shift | ✓ |
| Drive Axle | ✓ | Transmission Fluid | ✓ |
| Steering, Suspension & Brakes | | | |
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Suspension | | | |
| Shock Absorbers | ✓ | | |
| Electricals, Controls & Lights | | | |
| Keys | | | |
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ~ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| | | | |



| Right Hand Side Front Tyre | • | Right Hand Side Rear Tyre | • |
|----------------------------|----------|---------------------------|------|
| Spare Tyre | ~ | | |
| Life remaining | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <55% |
| Spare Tyre | <75% | | |
| | | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE