



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 INFINITI QX50 LUXURY | 99,841 KM

VIN: JNRBJ0RR0JM320193

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats

Basic Details

Yes	Specs	GCC	99841	Kilometers	
Semi Loaded	Option Type	(***)	3.7L	Engine	
All Wheel Drive	Drive	I-∳I I-∯I	Automatic	Transmission	P. C. N. D.
9.3 km/L mileage	Fuel Efficiency		SUV	Body Type	(<u>0-0</u>
Exterior Color Burgundy	Exterior Color		Alloy Wheels	Wheel Type	
6 Airbags	Number of Airbags	<i>"</i>	Leather Trim	Interior Trim	**
2 Keys	Number of keys	E	5 Seats	Seating Capacity	Å
			JNRBJ0RR0JM320193	VIN number	000

Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
360 degree Camera	✓	Navigation	~
Parking Sensors Front	✓	Parking Sensors Rear	~
Reverse Camera	✓	Traction Control	~
Front Camera	✓	Side Camera	~
Airbag Curtain Shield	~	Airbag Driver Front	✓


ABS	✓	Central Locking	~
Child Safety Locking	~		
© Comfort & Convenience			
Climate Control AC	~	Cruise Control	•
Memory Seats	•	Rear Armrest with cupholder	✓
Steering Mounted Audio Controls	•	Power Folding Mirrors	✓
Rear Defogger	✓	Central Armrest	✓
Automatic Headlights	~	Steering Column Adjuster	✓
Exteriors			
Fog Light Front	~	Roof Rails	•
Running Lights	~	Rear Bumper Spoiler	✓
Halogen Headlights	~	HID Headlights	•
್ರವ Entertainment			
Bluetooth Player	~	Infotainment System	✓
USB player			


150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A Pillar	~	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	~
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition Front Windshield Condition: Passenger Side/Stone Chip Mark<8mm	(!)	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor Door Skirting: Light Scuffing < 50mm	(!)	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition Light Scuffing < 50mm	(!)





Cup Holder	✓	Glove Box	•
Steering Wheel	✓	Sunvisor	•
Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	(!)	Manual Seat Movement	•
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Right Door: Light Scuffing/Disfiguration	!	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓
Tyres			
Tyres Condition			
	✓	Left Hand Side Rear Tyre	✓
Tyres Condition	✓	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	✓
Tyres Condition Left Hand Side Front Tyre			✓
Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre			✓✓
Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre	75%		<90%
Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre Life remaining	75% 490%	Right Hand Side Rear Tyre	<90% <85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE