


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2024 SUZUKI SWIFT**

**GL | 43,474 KM**

VIN: JS2ZC6C17R6500341

## Car highlights

### Good Tyre Condition

Tyre age less than 2 years

### Great Parking Assistance

Reverse Camera

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 43474 | Specs | Yes |
| Engine | 1.2L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | HATCHBACK | Fuel | Petrol |
| Wheel Type | Steel Wheels | Exterior Color | Exterior Color Orange |
| Interior Trim | Fabric Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | JS2ZC6C17R6500341 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Exteriors** | | | |
| Fog Light Front | ✓ | Running Lights | ✓ |
| Halogen Headlights | ✓ | | |
| **Safety & Security** | | | |
| Reverse Camera | ✓ | Traction Control | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |

| | | | |
|---|---|---|---|
| Central Locking | ✓ | Child Safety Locking | ✓ |
| **Comfort & Convenience** | | | |
| Steering Mounted Audio Controls | ✓ | Rear Defogger | ✓ |
| Steering Column Adjuster | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

Doors condition

| | | | |
|---|---|---|---|
| Front left door | ✓ | Front right door<br>Panel: Paint Chip-off < 5mm | ! |
| Rear left door | ✓ | Rear right door | ✓ |

Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender<br>Right Fender: Dent, Light Scuffing | ! |

Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

Front Bumper Condition

| | |
|---|---|
| Front Bumper | ✓ |

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm, Chip< 8mm | ! |

Hood Condition

| | |
|---|---|
| Hood<br>Bonnet: Low Visibility Dent < 30mm | ! |

Trunk Condition

| | |
|---|---|
| Trunk | ✓ |

Trunk conditon

| | |
|---|---|
| Trunk | ✓ |

Roof Condition

| | |
|---|---|
| Roof | ✓ |

Pillars Condition

| | | | |
|---|---|---|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |

| | | | |
|---|---|---|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |

Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield<br>Condition: Driver Side/Stone Chip Mark<5mm | ! | Rear Windshield | ✓ |

Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |

Cowl Top

| | |
|---|---|
| Cowl Top | ✓ |

Rear View Mirror Condition

| | | | |
|---|---|---|---|
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |

Alloy Wheel/ Rim

| | |
|---|---|
| Spare Alloy/ Rim Condition | ✓ |

| | | | |
|---|---|---|---|
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |

Panel Condition

| | |
|---|---|
| Rear Trunk Panel | ✓ |

## Engine & Transmission

Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |

Fuel System

| | | | |
|---|---|---|---|
| Fuel Tank | ✓ | | |

Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

## Steering, Suspension & Brakes

Steering

| | | | |
|---|---|---|---|
| Steering wheel | ✓ | | |

Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |

Suspension

| | | | |
|---|---|---|---|
| Shock Absorbers | ✓ | | |

## Electricals, Controls & Lights

Keys

| | | | |
|---|---|---|---|
| Master Key | ✓ | | |

Door Locks

| | | | |
|---|---|---|---|
| Child Safety Locking | ✓ | | |

Dashboard

| | | | |
|---|---|---|---|
| Instrument Panel | ✓ | | |

Airbags

| | | | |
|---|---|---|---|
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |

| | | | |
|---|---|---|---|
| Music System | ✓ | Camera | ✓ |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Glove Box | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |
| Grab Handle | ✓ | Carpet | ✓ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |

| | |
|---|---|
| Spare Tyre | ✓ |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <55% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <55% |
| Spare Tyre | <65% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE