



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 HONDA CR V

LX | 113,373 KM

VIN: 5J6RW5815JL700980

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat



Basic Details

 Kilometers	113373	 Specs	Yes
 Engine	2.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	5J6RW5815JL700980		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Steering Column Adjuster			
 Exteriors			

Running Lights	✓	Rear Bumper Spoiler	✓
Halogen Headlights	✓		
 Safety & Security			
Reverse Camera	✓	Traction Control	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Entertainment			
Bluetooth Player	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm, Paint Chip-off < 5mm	
-----------------	---	---	---

Rear left door		Rear right door Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm	
----------------	---	--	---

Fenders Condition

Left Fender		Right Fender Right Fender: Low Visual Dent, Light Scuffing	
-------------	---	---	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Dent, Light Scuffing	
--------------------	---	--	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar	⚠	Right A Pillar	✓
Inner Condition: Fair Use Wear			
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield		Rear Windshield	✓
Condition: Driver Side/Stone Chip Mark<5mm	⚠		
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	⚠		
Fair Use Wear/Crack<5mm			
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓

Panel Condition			
Rear Trunk Panel			
<hr/>			
Engine & Transmission			
Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Fuel System			
Fuel Tank			
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			
<hr/>			
Steering, Suspension & Brakes			
Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Suspension			
Shock Absorbers			
<hr/>			
Electricals, Controls & Lights			
Keys			
Master Key			
Button Faded			
Door Locks			
Child Safety Locking			
Dashboard			
Instrument Panel			

Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight			
Left: Low Brightness lamps	!	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	
		Right DRL: Low Brightness	!
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	
		Heater Not Working RHS	!
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	
		Box: Minor Crack/Fair Use Wear/ Scuffing	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery			
Driver Seat: Minor Fair Wear/Fade off, Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓

Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	!
		Front Left: Light Smudge/Disfiguration	
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<55%
RHS Front Tyre	<75%	RHS Rear Tyre	<45%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE