



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 MITSUBISHI PAJERO

GLS HIGHLINE | 60,699 KM

VIN: JE4MRY2MXNJ707541

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat




Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 60699 |  Specs | Yes |
|  Engine | 3.0L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 7.9 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Leather Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 7 Seats |  Number of keys | 2 Keys |
|  VIN number | JE4MRY2MXNJ707541 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors |  | Rear Defogger |  |
| Central Armrest |  | Steering Column Adjuster |  |
|  Exteriors | | | |

| | | | |
|--|---|---------------------|---|
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |
| Halogen Headlights | ✓ | HID Headlights | ✓ |
|  Safety & Security | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Traction Control | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Performance | | | |
| Differential Locks | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|---|---|
| Front left door |  | Front right door Panel: Paint Chip-off < 5mm |  |
| Rear left door |  | Rear right door Panel: Light Scuffing < 50mm |  |

Fenders Condition

| | | | |
|--|---|--------------|---|
| Left Fender Condition: Light Scuffing |  | Right Fender |  |
|--|---|--------------|---|

Quarter Panels Condition

| | | | |
|--------------------|--|---------------------|--|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|--|---------------------|--|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|-------------|---|
| Rear Bumper |  |
|-------------|---|

Hood Condition

| | |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|





Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|----------------------------|---|-----------------------------|---|
| Left A Pillar |  | Right A Pillar |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

| | | | |
|---------------------------------------|---|------------------------------|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | | | |
| Curtain not working | ! | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

| | | | |
|----------------------|---|-------------------------|---|
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | Rear Left AC Vent | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery Passenger Seat: Minor Smudge/Cracks | ! | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ! | Grab Handle | ✓ |

Front Left Door: Light Scuffing/ Disfiguration

Carpet



Headliner



Rear Left: Scuffing

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<85%

LHS Rear Tyre

<90%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE