



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2020 TOYOTA YARIS

SE | 126,155 KM

Car highlights

Fuel Efficient

Fuel efficient with 18.8 km/L



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 126155 |  Specs | Yes |
|  Engine | 1.5L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN | Fuel Efficiency | 18.8 km/L mileage |
|  Wheel Type | Steel Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 3 Keys |
|  VIN number | MHFB29F35L2103212 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|--------------------------|---|
|  Comfort & Convenience | | | |
| Cruise Control |  | Rear Defogger |  |
| Central Armrest |  | Steering Column Adjuster |  |
|  Safety & Security | | | |
| Parking Sensors Rear |  | Traction Control |  |
| Airbag Driver Front |  | ABS |  |

| | | | |
|--|---|----------------------|---|
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | USB player | ✓ |
|  Exteriors | | | |
| Halogen Headlights | ✓ | | |

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm |  |
|-----------------|---|--|---|

| | | | |
|----------------|---|--|---|
| Rear left door |  | Rear right door Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm |  |
|----------------|---|--|---|

Fenders Condition

| | | | |
|--|---|--------------|---|
| Left Fender Condition: Light Scuffing |  | Right Fender |  |
|--|---|--------------|---|

Quarter Panels Condition

| | | | |
|--------------------|---|---|---|
| Left Quarter Panel |  | Right Quarter Panel Condition: Low Visual Dent |  |
|--------------------|---|---|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|-------------|---|
| Rear Bumper |  |
|-------------|---|

Hood Condition

| | |
|--------------------------------------|---|
| Hood Bonnet: Paint Chip-off < 5mm |  |
|--------------------------------------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|-----------------------------|---|------------------------------|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel








Airbags

| | | | |
|-----------------------|---|---------------------|---|
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | License Plate Light | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Glove Box | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |
| Grab Handle | ✓ | Carpet | ! |
| | | Front Left Floor Mat: Smudge/Burn/Crack | |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

| | | | |
|----------------------------|---|---------------------------|---|
| Tyres Condition | | | |
| Left Hand Side Front Tyre |  | Left Hand Side Rear Tyre |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre |  | | |
| Life remaining | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <45% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <45% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE