



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 CHEVROLET GROOVE

LT | 51,166 KM

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play















Enjoy your drive with apple play



Amazing Comfort

Power driver seat



Basic Details

 Kilometers	51166	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	Fuel Efficiency	16.4 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LZWADAGA3PG017242		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Steering Column Adjuster			
 Safety & Security			
Parking Sensors Rear		Reverse Camera	






















Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓	HID Headlights	✓
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition			
Front left door		Front right door	
Rear left door		Rear right door	
		Panel: Light Scuffing < 50mm	
Fenders Condition			
Left Fender		Right Fender	
Quarter Panels Condition			
Left Quarter Panel		Right Quarter Panel	
Front Bumper Condition			
Front Bumper			
Rear Bumper Condition			
Rear Bumper			
Hood Condition			
Hood			
Trunk Condition			
Trunk			
Trunk conditon			
Trunk			
Pillars Condition			
Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	

Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	USB Charging Port	✓
Power/ Manual Windows	✓		








Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		



Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE