



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 TOYOTA RAV4

VXR | 88,115 KM

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat



Basic Details

| | | | |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers | 88115 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 14.2 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Silver |
|  Interior Trim | Leather Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | JTDWF9EV5HJ133134 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Rear Defogger |  | Central Armrest |  |
| Automatic Headlights |  | Steering Column Adjuster |  |
|  Exteriors | | | |





















| | | | |
|----------------------------------------------------------------------------------------------------------------|---|----------------------|---|
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Rear Bumper Spoiler | ✓ | Halogen Headlights | ✓ |
|  Safety & Security | | | |
| Navigation | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera | ✓ | Traction Control | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

| | | | |
|----------------------------|-------------------------------------------------------------------------------------|-------------------------------|---------------------------------------------------------------------------------------|
| Doors condition | | | |
| Front left door |  | Front right door |  |
| Rear left door |  | Rear right door |  |
| | | Panel: Low Visual Dent < 30mm | |
| Fenders Condition | | | |
| Left Fender |  | Right Fender |  |
| Quarter Panels Condition | | | |
| Left Quarter Panel |  | Right Quarter Panel |  |
| Front Bumper Condition | | | |
| Front Bumper |  | | |
| Rear Bumper Condition | | | |
| Rear Bumper |  | | |
| Hood Condition | | | |
| Hood |  | | |
| Trunk Condition | | | |
| Trunk |  | | |
| Trunk conditon | | | |
| Trunk |  | | |
| Roof Condition | | | |
| Roof |  | | |
| Pillars Condition | | | |
| Left A Pillar |  | Right A Pillar |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
| Right A to B Pillar |  | Left B Pillar |  |

| | | | |
|---------------------------------------|---|------------------------------|---|
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



| | | | |
|---------------------------------------|---|-------------------------|---|
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Navigation System | ✓ | Music System | ✓ |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ! | Daylight Running Lights | ✓ |
| Left Tail Lamp: Colour Low Brightness | | | |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|-------------------------------------------------------------|---|-------------------------------------|---|
| Dashboard And Instrument Panel | | Central Console | |
| Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted | ! | Gear Shift Knob: Knob Fair Use Wear | ! |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |

| | | | |
|------------------|---|-----------|---|
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <55% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <45% | RHS Rear Tyre | <85% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE