



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 MITSUBISHI ATTRAGE GLX HIGHLINE | 79,929 KM

Car highlights

Fuel Efficient

Fuel efficient with 20.2 km/L



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Steering Column Adjuster	~		
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Driver Front	•
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
Д ■ Entertainment			
Bluetooth Player	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	(!)	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		



Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight Left: Light Scuff Marks < 50mm	!	Interior Lights	•
Tail Light Cluster	~	License Plate Light	•
Fog Lights	✓		
Air Conditioning			
AC Cooling	~	AC Switch	✓
AC System Leaks	✓	Center AC Vent	•
Front Right AC Vent	✓	Heater	•
Parking Sensors	•	Rear Defogger	✓
USB Charging Port	~	Power/ Manual Windows	✓
Interiors & Luggage			
Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
0		Headliner	✓
Carpet		i leauiiilei	

Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Life remaining LHS Front Tyre <65% LHS Rear Tyre <65% RHS Front Tyre <55% RHS Rear Tyre <65% Spare Tyre <65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE