



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 FORD ECOSPORT

AMBIENTE | 103,742 KM

## Car highlights



### Cruise control

Cruise control to drive with ease & comfort



### Great Parking Assistance

Reverse Camera

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Music System

Enjoy your drive with music system



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>103742</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel Efficiency	<b>14.7 km/L mileage</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MAJFK1BZ8KAG22096</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>	
Rear Bumper Spoiler	
 <b>Performance</b>	
Hill Descent Control	
 <b>Safety &amp; Security</b>	
Reverse Camera	
Traction Control	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
<b>Comfort &amp; Convenience</b>			
Steering Mounted Audio Controls		Rear Defogger	
Steering Column Adjuster			
<b>Entertainment</b>			
Bluetooth Player		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Moulding: Colour mismatch/ Low Brightness

Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Chip< 8mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor			
Door Skirting: Colour Mismatch/ Fade/ Fair Use Wear	!	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	!		
Fair Use Wear/Crack<5mm			
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls			
Cruise Control	✓		
Infotainment Display	✓	OBD Connector	✓

## Navigation System

Condition: Available - Google Map Only



## Music System



## Camera



## Lights

### Headlight

Left: Light Scuff Marks < 50mm



### Interior Lights



### Tail Light Cluster

Right Tail Lamp: Crack / Fair Use Wear <



5mm

### License Plate Light



## Air Conditioning

### AC Cooling



### AC Switch



### AC System Leaks



### Center AC Vent



### Front Right AC Vent



### Heater



### USB Charging Port



### Power/ Manual Windows



### Memory Seats



## Interiors & Luggage

### Dashboard And Instrument Panel



### Central Console



### Cup Holder



### Glove Box



### Steering Wheel



### Sunvisor



### Seat Upholstery



### Manual Seat Movement



### Seat Belts



### Head Rest



### Door Controls And Trim



### Grab Handle



### Carpet



### Headliner



### Rear View Mirror



### Toolkit



## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<75%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE