

# **Car Report**



#### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 NISSAN X TRAIL

S | 77,493 KM

VIN: JN1BT2MU3NW024681

## Car highlights



### **Great condition**

Car has low imperfections



**Cruise control** 

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

## **Basic Details**

Kilometers	77493	GCC	Specs	Yes
Engine	2.5L	**************************************	Option Type	Basic
Transmission	Automatic	ા-©-ા ા-①-ા	Drive	Front Wheel Drive
Body Type	SUV	<u>P</u>	Fuel	Petrol
🛞 Wheel Type	Alloy Wheels		Exterior Color	Exterior Color Grey
Interior Trim	Fabric Trim	Č,	Number of Airbags	2 Airbags
A Seating Capacity	5 Seats	R	Number of keys	2 Keys
VIN number JN1	BT2MU3NW024681			

# Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Le Comfort & Convenience			
Cruise Control	~	Rear Armrest with cupholder	~
Steering Mounted Audio Controls	~	Rear Defogger	~
Central Armrest	~	Steering Column Adjuster	~
Exteriors			
Running Lights	<ul> <li></li> </ul>	Rear Bumper Spoiler	•

Halogen Headlights	~		
່ງ Safety & Security			
Traction Control	~	Airbag Driver Front	~
ABS	~	Central Locking	~
Child Safety Locking	~		
Bluetooth Player	~	USB player	~

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed			
അ Exterior			
Doors condition			
Front left door	~	Front right door Panel: Paint Chip-off < 5mm	!
Rear left door	•	Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	(!)
Fenders Condition			
Left Fender Condition: Paint Chip-off	(!)	Right Fender	~
Quarter Panels Condition			
Left Quarter Panel	~	Right Quarter Panel	<ul> <li></li> </ul>
Front Bumper Condition			
Front Bumper	<ul> <li></li> </ul>		
Rear Bumper Condition			
Rear Bumper	<ul> <li></li> </ul>		
Hood Condition			
Hood	<ul> <li></li> </ul>		
Trunk Condition			
Trunk	<ul> <li></li> </ul>		
Trunk conditon			
Trunk	<ul> <li></li> </ul>		
Roof Condition			
Roof	<ul> <li></li> </ul>		
Pillars Condition			
Left A Pillar	<ul> <li></li> </ul>	Right A Pillar	~

Left A to B Pillar Beading	~	Right A to B Pillar Beading	~
Right A to B Pillar	~	Left B Pillar	~
Left B Pillar Trim	~	Left B to C Pillar Beading	~
Right C Pillar Trim	~	Right B to C Pillar	~
Right B to C Pillar Beading	~	Left C Pillar	~
Running Board Condition			
Left Running Board	<ul> <li>Image: A start of the start of</li></ul>	Right Running Board	~
Windshield Condition			
Front Windshield	<ul> <li></li> </ul>	Rear Windshield	~
Structural Assessment			
Chassis Condition	<ul> <li>Image: A start of the start of</li></ul>	Apron	<ul> <li></li> </ul>
Boot Floor	<ul> <li>Image: A start of the start of</li></ul>	Firewall Condition	~
Cowl Top	~	Head Light Support Condition	<ul> <li></li> </ul>
Cowl Top			
Cowl Top	~		
Rear View Mirror Condition			
Left Hand Side Mirror	~	Left Side Mirror	~
Right Side Mirror	<ul> <li>Image: A start of the start of</li></ul>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<ul> <li>Image: A start of the start of</li></ul>	Left Rear Alloy/ Rim	~
Right Front Alloy/ Rim	~	Right Rear Alloy/ Rim	~
Spare Alloy/ Rim Condition	~		
Wheel cover	~	Antenna	~
Grill Condition	~	Monogram	~
Window Glass	~	Wiper	•
Panel Condition			
Rear Trunk Panel	~		

# Engine & Transmission

Engine			
Engine Body	<ul> <li></li> </ul>	Engine Performance	<ul> <li></li> </ul>
Engine Oil (Condition & Level)	<ul> <li></li> </ul>	Exhaust System	<ul> <li></li> </ul>
Radiator Condition	<ul> <li>Image: A start of the start of</li></ul>	Radiator Coolant	<ul> <li>Image: A start of the start of</li></ul>
Fuel System			
Fuel Tank	<ul> <li>Image: A start of the start of</li></ul>		
Transmission Operation			
Gear Shifting	<ul> <li>Image: A start of the start of</li></ul>	Drive Axle	<ul> <li>Image: A start of the start of</li></ul>
Transmission Fluid	<ul> <li>Image: A start of the start of</li></ul>		

## Steering, Suspension & Brakes

Steering			
Steering wheel	<ul> <li></li> </ul>		
Brake System			
Parking Brake	<ul> <li></li> </ul>	Brake Master Cylinder	<ul> <li></li> </ul>
Brake Disc & Brake Pad	<ul> <li></li> </ul>	Brake Fluid	<ul> <li></li> </ul>
Suspension			
Shock Absorbers	<ul> <li></li> </ul>		

Electricals, Controls & Lights			
Keys			
Master Key	<ul> <li>Image: A start of the start of</li></ul>	Spare Key(s)	~
Door Locks			
Child Safety Locking	<ul> <li>Image: A start of the start of</li></ul>		
Dashboard			
Instrument Panel	<ul> <li>Image: A start of the start of</li></ul>		
Airbags			
Airbags	<ul> <li></li> </ul>		

Controls	~	Cruise Control	~
Infotainment Display	<ul> <li>Image: A start of the start of</li></ul>	OBD Connector	~
Music System	<ul> <li>Image: A start of the start of</li></ul>		
Lights			
Headlight	<ul> <li></li> </ul>	Interior Lights	~
Tail Light Cluster	<ul> <li>Image: A start of the start of</li></ul>	Daylight Running Lights	<ul> <li>Image: A start of the start of</li></ul>
License Plate Light	<ul> <li></li> </ul>		
Air Conditioning			
AC Cooling	~	AC Switch	~
AC System Leaks	<ul> <li></li> </ul>	Center AC Vent	~
Front Right AC Vent	<ul> <li>Image: A start of the start of</li></ul>	Heater	~
Rear Blower Switch	~		
USB Charging Port	<ul> <li>Image: A start of the start of</li></ul>	Power/ Manual Windows	~

## ≜ Interiors & Luggage

Dashboard And Instrument Panel	<ul> <li></li> </ul>	Central Console	<ul> <li></li> </ul>
Cup Holder	<ul> <li></li> </ul>	Glove Box	<ul> <li></li> </ul>
Steering Wheel	<ul> <li></li> </ul>	Sunvisor	~
Seat Upholstery	<ul> <li>Image: A start of the start of</li></ul>	Manual Seat Movement	<ul> <li></li> </ul>
Seat Belts	<ul> <li>Image: A start of the start of</li></ul>	Head Rest	<ul> <li>Image: A start of the start of</li></ul>
Door Controls And Trim	<ul> <li>Image: A start of the start of</li></ul>	Grab Handle	~
Carpet	<ul> <li>Image: A start of the start of</li></ul>	Headliner	~
Rear View Mirror	<ul> <li></li> </ul>	Toolkit	<ul> <li></li> </ul>



#### Tyres Condition

Left Hand Side Front Tyre	<ul> <li></li> </ul>	Left Hand Side Rear Tyre	<ul> <li></li> </ul>
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	<ul> <li>Image: A start of the start of</li></ul>
Spare Tyre	~		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE