



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 10,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 MITSUBISHI ECLIPSE CROSS**

**HIGH LINE | 79,444 KM**

VIN: JE4LS5148LZ701123

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 79444             |  Specs             | Yes                 |
|  Engine           | 1.5L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SUV               |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 7 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | JE4LS5148LZ701123 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                             |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                             |                                                                                       |
| Heads up Display                                                                                                     |  | Climate Control AC          |  |
| Cruise Control                                                                                                       |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls                                                                                      |  | Power Folding Mirrors       |  |
| Rear Defogger                                                                                                        |  | Central Armrest             |  |
| Automatic Headlights                                                                                                 |  | Steering Column Adjuster    |  |



## Exteriors

Fog Light Front



Roof Rails



Running Lights



Rear Bumper Spoiler



LED Headlights



## Safety & Security

Lane Departure Warning  
System



Navigation



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



Collision Warning System



Traction Control



Airbag Curtain Shield



Airbag Knees



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Performance

Paddle Shift



## Entertainment

Bluetooth Player



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                                                         |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door                                                        |  |
| Rear left door  |  | Rear right door<br>Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm |  |

### Fenders Condition

|                                                           |                                                                                   |                                    |                                                                                     |
|-----------------------------------------------------------|-----------------------------------------------------------------------------------|------------------------------------|-------------------------------------------------------------------------------------|
| Left Fender<br>Condition: Low Visual Dent, Light Scuffing |  | Right Fender<br>Right Fender: Dent |  |
|-----------------------------------------------------------|-----------------------------------------------------------------------------------|------------------------------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                    |                     |                                                                                      |
|--------------------|------------------------------------------------------------------------------------|---------------------|--------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|------------------------------------------------------------------------------------|---------------------|--------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|                                                                     |                                                                                     |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Roof<br>Roof Moulding Condition: Minor Rubber Beading Fair Use Wear |  |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------------|

### Pillars Condition

|               |                                                                                     |                |                                                                                       |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|
| Left A Pillar |  | Right A Pillar |  |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|

|                                       |   |                                               |   |
|---------------------------------------|---|-----------------------------------------------|---|
| Left A to B Pillar Beading            | ✓ | Right A to B Pillar Beading                   | ✓ |
| Right A to B Pillar                   | ✓ | Left B Pillar                                 | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading                    | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar                           | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                                 | ✓ |
| Running Board Condition               |   |                                               |   |
| Left Running Board                    | ✓ | Right Running Board                           |   |
|                                       |   | Front Right Sill Trim: Low Visual Dent < 50mm | ! |
| Sunroof Glass Condition (If Equipped) |   |                                               |   |
| Sun Roof Glass                        | ✓ |                                               |   |
| Windshield Condition                  |   |                                               |   |
| Front Windshield                      | ✓ | Rear Windshield                               | ✓ |
| Structural Assessment                 |   |                                               |   |
| Chassis Condition                     | ✓ | Apron                                         | ✓ |
| Boot Floor                            | ✓ | Firewall Condition                            | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition                  | ✓ |
| Cowl Top                              |   |                                               |   |
| Cowl Top                              | ✓ |                                               |   |
| Rear View Mirror Condition            |   |                                               |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror                              | ✓ |
| Right Side Mirror                     | ✓ |                                               |   |
| Alloy Wheel/ Rim                      |   |                                               |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim                          | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim                         | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                                               |   |
| Antenna                               | ✓ | Grill Condition                               | ! |
|                                       |   | Light Scuffing < 50mm                         |   |
| Monogram                              | ✓ | Window Glass                                  | ✓ |

|                  |   |
|------------------|---|
| Wiper            | ✓ |
| Panel Condition  |   |
| Rear Trunk Panel | ✓ |

## Engine & Transmission

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓     |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition ✓ |
| Radiator Coolant               | ✓ |                      |
| Fuel System                    |   |                      |
| Fuel Tank                      | ✓ |                      |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Gear shift ✓         |
| Drive Axle                     | ✓ | Transmission Fluid ✓ |

## Steering, Suspension & Brakes

|                        |   |                         |
|------------------------|---|-------------------------|
| Steering               |   |                         |
| Steering wheel         | ✓ |                         |
| Brake System           |   |                         |
| Parking Brake          | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓           |
| Suspension             |   |                         |
| Shock Absorbers        | ✓ |                         |

## Electricals, Controls & Lights

|                      |   |                |
|----------------------|---|----------------|
| Keys                 |   |                |
| Master Key           | ✓ | Spare Key(s) ✓ |
| Door Locks           |   |                |
| Child Safety Locking | ✓ |                |

|                                       |   |                         |   |
|---------------------------------------|---|-------------------------|---|
| Dashboard                             |   |                         |   |
| Instrument Panel                      | ✓ |                         |   |
| Airbags                               |   |                         |   |
| Airbags                               | ✓ |                         |   |
| Controls                              | ✓ | Cruise Control          | ✓ |
| Heads Up Display                      | ✓ | Infotainment Display    | ✓ |
| OBD Connector                         | ✓ | Radar (If Equipped)     | ✓ |
| Navigation System                     | ✓ | Music System            | ✓ |
| Sunroof Operation                     |   |                         |   |
| Sunroof                               | ✓ |                         |   |
| Lights                                |   |                         |   |
| Headlight                             |   | Interior Lights         | ✓ |
| Left: Light Scuff Marks < 50mm        | ! |                         |   |
| Tail Light Cluster                    |   | Daylight Running Lights | ✓ |
| Left Tail Lamp: Light Scuffing < 50mm | ! |                         |   |
| License Plate Light                   | ✓ | Fog Lights              | ✓ |
| Air Conditioning                      |   |                         |   |
| AC Cooling                            | ✓ | AC Switch               | ✓ |
| AC System Leaks                       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent                   | ✓ | Heater                  | ✓ |
| Parking Sensors                       | ✓ | Rear Defogger           | ✓ |
| USB Charging Port                     | ✓ | Power/ Manual Windows   | ✓ |
| Seat Heaters                          | ✓ |                         |   |

## Interiors & Luggage

|                                                             |   |                                |   |
|-------------------------------------------------------------|---|--------------------------------|---|
| Dashboard And Instrument Panel                              |   | Central Console                |   |
| Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted | ! | Gear Shift Knob: Buttons Faded | ! |

|                                                             |   |                      |   |
|-------------------------------------------------------------|---|----------------------|---|
| Cup Holder                                                  | ✓ | Glove Box            | ✓ |
| Steering Wheel                                              | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                                             |   |                      |   |
| Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off | ! | Manual Seat Movement | ✓ |
| Seat Belts                                                  | ✓ | Head Rest            | ✓ |
| Door Controls And Trim                                      | ✓ | Grab Handle          | ✓ |
| Carpet                                                      | ✓ | Headliner            | ✓ |
| Rear View Mirror                                            | ✓ | Toolkit              | ✓ |

## Tyres

### Tyres Condition

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <85% | LHS Rear Tyre             | <85% |
| RHS Front Tyre             | <85% | RHS Rear Tyre             | <85% |
| Spare Tyre                 | <75% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE