

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 FORD ESCAPE

SE | 88,356 KM

VIN: WF0BM4AF1JVS33099

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Music System

Enjoy your drive with music system

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls

Amazing Comfort

Power driver seat

Basic Details

Kilometers	88356	Specs	Yes
Engine	2L	Option Type	Semi Loaded
Transmission	Automatic	Drive	All Wheel Drive
Body Type	SUV	Fuel Efficiency	11.9 km/L mileage
Wheel Type	Steel Wheels	Exterior Color	Exterior Color Black
Interior Trim	Fabric Trim	Number of Airbags	6 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	WF0BM4AF1JVS33099		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Cruise Control	✓	Steering Mounted Audio Controls	✓
Exteriors			
Fog Light Front	✓		
Entertainment			

USB Charging Port	✓
Infotainment System	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front left door	✓	Front right door Panel: Light Scuffing < 50mm	!
Rear left door Panel: Dent	!	Rear right door Panel: Light Scuffing < 50mm	!

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel Condition: Dent	!	Right Quarter Panel	✓

Front Bumper Condition

Front Bumper	✓

Rear Bumper Condition

Rear Bumper	✓

Hood Condition

Hood Bonnet: Dent > 30mm	!

Trunk Condition

Trunk	✓

Trunk conditon

Trunk	✓

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓

Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top Beading: Crack/Fair Use Wear>50mm	!	Head Light Support Condition	✓

Cowl Top

Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		

Alloy Wheel/ Rim

Spare Alloy/ Rim Condition	✓

Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓

Wiper

Rear Wiper Blade: Crack/ Fair Use Wear	!

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Fuel System

Fuel Tank	✓		

Transmission Operation

Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering

Steering wheel	✓		

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Suspension

Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s) Remote Functions Not Responding	!

Door Locks

Child Safety Locking	✓		

Dashboard

Instrument Panel	✓		

Airbags

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓

Music System	

Lights

Headlight Left: Scuff Marks > 50mm	Interior Lights
Tail Light Cluster	License Plate Light
Fog Lights	

Air Conditioning

AC Cooling	AC Switch
AC System Leaks	Center AC Vent
Front Right AC Vent	Heater
Rear Blower Switch	
Power/ Manual Windows	

Interiors & Luggage

Dashboard And Instrument Panel	Central Console Gear Shift Knob: Knob Missing
Glove Box	Steering Wheel Steering Wheel Fair Use Wear
Sunvisor	Seat Upholstery
Manual Seat Movement	Seat Belts
Head Rest	Door Controls And Trim
Grab Handle	Carpet
Headliner	Rear View Mirror Damaged Mirror Casing
Toolkit	

Tyres

Tyres Condition

Left Hand Side Rear Tyre	Right Hand Side Front Tyre

Right Hand Side Rear Tyre	✓	Spare Tyre	✓

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE