



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 MG RX5

LUXURY | 18,199 KM

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play















Enjoy your drive with apple play



Amazing Comfort












Power driver seat





Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 18199 |  Specs | Yes |
|  Engine | 1.5L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 12.8 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | LSJA24U92RS030924 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|--|--|--|
|  Safety & Security | | | |
| 360 degree Camera  | | Navigation  | |
| Parking Sensors Front  | | Parking Sensors Rear  | |
| Reverse Camera  | | Traction Control  | |
| Front Camera  | | Side Camera  | |
| Airbag Curtain Shield  | | Airbag Driver Front  | |

| | | | |
|--|---|---------------------------------|---|
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Comfort & Convenience | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Rear Armrest with cupholder | ✓ | Steering Mounted Audio Controls | ✓ |
| Power Folding Mirrors | ✓ | Power Tailgate/ Power Trunk | ✓ |
| Rear Defogger | ✓ | Central Armrest | ✓ |
| Automatic Headlights | ✓ | Steering Column Adjuster | ✓ |
|  Exteriors | | | |
| Roof Rails | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | LED Headlights | ✓ |
|  Performance | | | |
| Hill Descent Control | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | USB Charging Port | ✓ |
| Infotainment System | ✓ | USB player | ✓ |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior


Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door Panel: Light Scuffing < 50mm |  |
| Rear left door |  | Rear right door |  |

Fenders Condition

| | | | |
|-------------|---|--|---|
| Left Fender |  | Right Fender Right Fender: Scuffing |  |
|-------------|---|--|---|


Quarter Panels Condition

| | | | |
|--------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|---|---------------------|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|------------------------------------|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm | |

Hood Condition

| | |
|------------------------------|---|
| Hood |  |
| Bonnet: Paint Chip-off < 5mm | |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|





Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|----------------------------|---|-----------------------------|---|
| Left A Pillar |  | Right A Pillar |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

| | | | |
|---------------------------------------|---|--|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition Light Scuffing < 50mm | ! |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



| | | | |
|----------------------|---|--|---|
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Navigation System | ✓ | Music System | ✓ |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights Right DRL: Low Brightness | ! |
| License Plate Light | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|---|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | | | |
| Rear Right Seat: Leather/ Fabric Fair Use Wear | ! | Manual Seat Movement | ✓ |

| | | | |
|------------------------|---|-------------|---|
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE