



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 MITSUBISHI MONTERO SPORT

GLS PREMIUM | 78,375 KM

VIN: MMEMCY1X9MH000876

Car highlights



Four wheel drive

This car has a Four wheel drive



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	78375	 Specs	Yes
 Engine	3.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	8.5 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Leather Trim	 Number of Airbags	7 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MMEMCY1X9MH000876		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		360 degree Camera	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Traction Control	
Front Camera		Side Camera	
Airbag Curtain Shield		Airbag Knees	

Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Rear Armrest with cupholder	✓	Steering Mounted Audio Controls	✓
Power Folding Mirrors	✓	Power Tailgate/ Power Trunk	✓
Rear Defogger	✓	Central Armrest	✓
Steering Column Adjuster	✓		
 Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
LED Headlights	✓		
 Performance			
Paddle Shift	✓	Hill Descent Control	✓
Differential Locks	✓		
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
USB Charging Port	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm, Low Visibility	
		Dent < 30mm	

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing		Right Fender: Light Scuffing	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	--	---------------------	--

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
Bonnet: Low Visibility Dent < 30mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Radar (If Equipped)	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	ⓘ	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓



Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	ⓘ	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel			
Steering Wheel Fair Use Wear	ⓘ	Sunvisor	✓

Seat Upholstery Driver Seat: Minor Smudge/ Cracks	ⓘ	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE