



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2021 HYUNDAI PALISADE**

**PREMIUM+ | 53,520 KM**

VIN: KMHR381E7MU268951

## **Car highlights**



### **Manufacturer warranty**

Till 03/03/2026 (Not verified)



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**












Power driver seat, Memory Seats & more





Basic Details

|  |                   |   |                     |
|--|-------------------|---|---------------------|
|  Kilometers       | 53520             |  Specs             | Yes                 |
|  Engine           | 3.8L              |  Option Type       | Fully Loaded        |
|  Transmission     | Automatic         |  Drive             | All Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 8 Airbags           |
|  Seating Capacity | 8 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | KMHR381E7MU268951 |   |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Heads up Display   |  | Climate Control AC              |  |
| Cruise Control   |  | Memory Seats                    |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors  |  | Ventilated Seat                 |  |
| Power Tailgate/ Power Trunk  |  | Rear Defogger                   |  |

















|  |   |                          |   |
|--|---|--------------------------|---|
| Central Armrest  | ✓ | Remote Engine Start      | ✓ |
| Automatic Headlights   | ✓ | Steering Column Adjuster | ✓ |
|  <b>Safety &amp; Security</b> |   |                          |   |
| Adaptive cruise control  | ✓ | 360 degree Camera        | ✓ |
| Lane Departure Warning System  | ✓ | Navigation               | ✓ |
| Parking Sensors Front  | ✓ | Parking Sensors Rear     | ✓ |
| Reverse Camera   | ✓ | Blind Spot Monitor       | ✓ |
| Collision Warning System   | ✓ | Traction Control         | ✓ |
| Front Camera   | ✓ | Side Camera              | ✓ |
| Airbag Curtain Shield  | ✓ | Airbag Driver Front      | ✓ |
| ABS  | ✓ | Central Locking          | ✓ |
| Child Safety Locking   | ✓ |                          |   |
|  <b>Performance</b>         |   |                          |   |
| Paddle Shift   | ✓ | Hill Descent Control     | ✓ |
|  <b>Exteriors</b>           |   |                          |   |
| Roof Rails   | ✓ | Running Lights           | ✓ |
| Rear Bumper Spoiler  | ✓ | LED Headlights           | ✓ |
|  <b>Entertainment</b>       |   |                          |   |
| Bluetooth Player   | ✓ | Apple Play               | ✓ |
| USB Charging Port  | ✓ | Infotainment System      | ✓ |
| USB player   | ✓ |                          |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|                          |   |   |   |
|--------------------------|---|---|---|
| Doors condition          |   |   |   |
| Front left door          |    | Front right door  |   |
|                          |   | Panel: Light Scuffing < 50mm, Low Visibility<br>Dent < 30mm |    |
| Rear left door           |    | Rear right door   |   |
|                          |   | Panel: Low Visual Dent < 30mm, Light<br>Scuffing < 50mm     |    |
| Fenders Condition        |   |   |   |
| Left Fender              |    | Right Fender  |   |
|                          |   | Right Fender: Low Visual Dent, Light Scuffing               |    |
| Quarter Panels Condition |   |   |   |
| Left Quarter Panel       |  | Right Quarter Panel   |  |
| Front Bumper Condition   |   |   |   |
| Front Bumper             |  |   |   |
| Rear Bumper Condition    |   |   |   |
| Rear Bumper              |  |   |   |
| Hood Condition           |   |   |   |
| Hood                     |  |   |   |
| Trunk Condition          |   |   |   |
| Trunk                    |  |   |   |
| Trunk conditon           |   |   |   |
| Trunk                    |  |   |   |
| Roof Condition           |   |   |   |
| Roof                     |  |   |   |
| Pillars Condition        |   |   |   |
| Left A Pillar            |  | Right A Pillar  |  |

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading  | ✓ |
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   | Monogram                     | ✓ |
| Light Scuffing < 50mm       | ! |                              |   |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Airbags               | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Heads Up Display      | ✓ | Infotainment Display    | ✓ |
| OBD Connector         | ✓ | Navigation System       | ✓ |
| Music System          | ✓ |                         |   |
| Sunroof Operation     |   |                         |   |
| Sunroof               | ✓ |                         |   |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| License Plate Light   | ✓ | Fog Lights              | ✓ |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC Switch               | ✓ |
| AC System Leaks       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent   | ✓ | Heater                  | ✓ |
| Rear Blower Switch    | ✓ | Rear Left AC Vent       | ✓ |
| Rear Defogger         | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows | ✓ | Seat Heaters            | ✓ |
| Memory Seats          | ✓ |                         |   |

## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder                     | ✓ | Glove Box       | ✓ |
| Steering Wheel                 | ✓ | Sunvisor        | ✓ |



|                        |   |                      |   |
|------------------------|---|----------------------|---|
| Seat Upholstery        | ✓ | Manual Seat Movement | ✓ |
| Seat Belts             | ✓ | Head Rest            | ✓ |
| Door Controls And Trim | ✓ | Grab Handle          | ✓ |
| Carpet                 | ✓ | Headliner            | ✓ |
| Rear View Mirror       | ✓ | Toolkit              | ✓ |

## Tyres

Tyres Condition

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <85% |
| RHS Front Tyre             | <75% | RHS Rear Tyre             | <85% |
| Spare Tyre                 | <75% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE