



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2023 TOYOTA RAV4 EX | 62,058 KM

# **Car highlights**



#### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

## **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



## Apple play


Enjoy your drive with apple play



## **Amazing Comfort**


Power driver seat

#### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Parking Sensors Rear	<b>✓</b>	Traction Control	~
Airbag Curtain Shield	~	Airbag Knees	<b>✓</b>
Airbag Driver Front	~	ABS	<b>✓</b>
Central Locking	~	Child Safety Locking	~
Exteriors			
Running Lights	~	Rear Bumper Spoiler	~
LED Headlights	~		
√a Entertainment			
Bluetooth Player	~	Apple Play	<b>✓</b>
Infotainment System	<b>✓</b>	USB player	

## **150 Point Detailed Inspection Report**


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality




Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>✓</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>✓</b>
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel cover	<b>✓</b>	Antenna	<b>~</b>
Grill Condition	<b>✓</b>	Monogram	<b>✓</b>
Window Glass	<b>✓</b>	Wiper	<b>~</b>
		·	
Panel Condition			
Rear Trunk Panel	<b>✓</b>		

# **Engine & Transmission**

Engine





Right Hand Side Front Tyre	•	Right Hand Side Rear Tyre	~
Spare Tyre	<b>~</b>		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<85%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE