



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 MG ZS**

**STD | 64,095 KM**

## **Car highlights**

### **Fuel Efficient**

Fuel efficient with 17.2 km/L



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**















Enjoy your drive with apple play



### **Amazing Comfort**










Power driver seat

Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 64095             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               | Fuel Efficiency   | 17.2 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | LSJW74U35PZ045067 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Cruise Control   |  | Steering Mounted Audio Controls |  |
| Rear Defogger  |  | Central Armrest                 |  |
| Steering Column Adjuster   |  |                                 |   |
|  <b>Safety &amp; Security</b>     |   |                                 |   |
| Parking Sensors Rear   |  | Reverse Camera                  |  |

|  |   |                     |   |
|--|---|---------------------|---|
| Traction Control   | ✓ | Airbag Driver Front | ✓ |
| ABS  | ✓ | Central Locking     | ✓ |
| Child Safety Locking   | ✓ |                     |   |
|  <b>Exteriors</b>     |   |                     |   |
| Roof Rails   | ✓ | Running Lights      | ✓ |
| Rear Bumper Spoiler  | ✓ | LED Headlights      | ✓ |
|  <b>Performance</b>   |   |                     |   |
| Hill Descent Control   | ✓ |                     |   |
|  <b>Entertainment</b> |   |                     |   |
| Bluetooth Player   | ✓ | Apple Play          | ✓ |
| Android Auto Play  | ✓ | USB Charging Port   | ✓ |
| Infotainment System  | ✓ | USB player          | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

|                 |   |                  |   |
|-----------------|---|------------------|---|
| Front left door |  | Front right door |  |
|-----------------|---|------------------|---|

|                |   |                               |   |
|----------------|---|-------------------------------|---|
| Rear left door |  | Rear right door               |  |
|                |   | Panel: Low Visual Dent < 30mm |   |

Fenders Condition

|                            |   |              |   |
|----------------------------|---|--------------|---|
| Left Fender                |  | Right Fender |  |
| Condition: Low Visual Dent |   |              |   |

Quarter Panels Condition

|                    |   |                            |   |
|--------------------|---|----------------------------|---|
| Left Quarter Panel |  | Right Quarter Panel        |  |
|                    |   | Condition: Low Visual Dent |   |

Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

|             |   |
|-------------|---|
| Rear Bumper |  |
|-------------|---|

Hood Condition

|      |   |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

|               |   |                |   |
|---------------|---|----------------|---|
| Left A Pillar |  | Right A Pillar |  |
|---------------|---|----------------|---|

|                            |   |                             |   |
|----------------------------|---|-----------------------------|---|
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
|----------------------------|---|-----------------------------|---|

|                             |   |                              |   |
|-----------------------------|---|------------------------------|---|
| Right A to B Pillar         | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                | ✓ |
| Running Board Condition     |   |                              |   |
| Left Running Board          | ✓ | Right Running Board          | ✓ |
| Windshield Condition        |   |                              |   |
| Front Windshield            | ✓ | Rear Windshield              | ✓ |
| Structural Assessment       |   |                              |   |
| Chassis Condition           | ✓ | Apron                        | ✓ |
| Boot Floor                  | ✓ | Firewall Condition           | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                    |   |                              |   |
| Cowl Top                    | ✓ |                              |   |
| Rear View Mirror Condition  |   |                              |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror           | ✓ |                              |   |
| Alloy Wheel/ Rim            |   |                              |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                              |   |
| Wheel cover                 | ✓ | Antenna                      | ✓ |
| Grill Condition             |   | Monogram                     | ✓ |
| Light Scuffing < 50mm       | ! |                              |   |
| Window Glass                | ✓ | Wiper                        | ✓ |
| Panel Condition             |   |                              |   |
| Rear Trunk Panel            | ✓ |                              |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)

Manual Key Not Available



### Door Locks

Child Safety Locking



### Dashboard

Instrument Panel



### Airbags

Airbags



|                                      |   |  |   |
|--------------------------------------|---|--|---|
| Controls                             | ✓ | Cruise Control                                       | ✓ |
| Infotainment Display                 | ✓ | OBD Connector  | ✓ |
| Music System                         | ✓ | Camera   | ✓ |
| Lights                               |   |  |   |
| Headlight                            | ✓ | Interior Lights                                      | ✓ |
| Tail Light Cluster                   | ✓ | Daylight Running Lights<br>Right DRL: Low Brightness | ! |
| License Plate Light                  | ✓ |  |   |
| Air Conditioning                     |   |  |   |
| AC Cooling                           | ✓ | AC Switch  | ✓ |
| AC System Leaks                      | ✓ | Center AC Vent                                       | ✓ |
| Front Right AC Vent<br>Fair Use Wear | ! | Heater   | ✓ |
| Rear Blower Switch                   | ✓ |  |   |
| Parking Sensors                      | ✓ | Rear Defogger  | ✓ |
| USB Charging Port                    | ✓ | Power/ Manual Windows                                | ✓ |

## Interiors & Luggage

|                                |   |  |   |
|--------------------------------|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console                                | ✓ |
| Glove Box                      | ✓ | Steering Wheel<br>Steering Wheel Fair Use Wear | ! |
| Sunvisor                       | ✓ | Seat Upholstery                                | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts                                     | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim                         | ✓ |
| Grab Handle                    | ✓ | Carpet   | ✓ |
| Headliner                      | ✓ | Rear View Mirror                               | ✓ |





## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<45%

LHS Rear Tyre

<65%

RHS Front Tyre

<45%

RHS Rear Tyre

<45%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE