

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 SUZUKI CIAZ

GL | 45,653 KM

Car highlights

Good Tyre Condition

Tyre age less than 2 years

Great Parking Assistance

Reverse Camera

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	45653	Specs	Yes
Engine	1.5L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel Efficiency	16.7 km/L mileage
Wheel Type	Steel Wheels	Exterior Color	Exterior Color Grey
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MA3VC7A16RA494818		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Rear Armrest with cupholder	✓	Steering Mounted Audio Controls	✓
Rear Defogger	✓	Central Armrest	✓
Steering Column Adjuster	✓		
Safety & Security			
Reverse Camera	✓	Traction Control	✓

Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		
Exteriors			
Halogen Headlights	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front left door	Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm
Rear left door	Rear right door Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender Condition: Light Scuffing	Right Fender Right Fender: Light Scuffing

Quarter Panels Condition

Left Quarter Panel	Right Quarter Panel Condition: Light Scuffing

Front Bumper Condition

Front Bumper

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk

Trunk conditon

Trunk

Roof Condition

Roof

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board Condition: Dent	!	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓

Cowl Top

Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓

Panel Condition

Rear Trunk Panel ✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Fuel System

Fuel Tank ✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering

Steering wheel ✓

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓

Door Locks

Child Safety Locking ✓

Dashboard

Instrument Panel ✓

Airbags

Airbags	✓		
Controls	✓	Infotainment Display	✓
OBD Connector	✓	Music System	✓
Camera Reverse Camera: Feed not Proper	!		

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓

Air Conditioning

AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE