


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2020 CHEVROLET SPARK**

**LS | 107,520 KM**

VIN: KL1CD6CA1LC477619

## Car highlights

### Fuel Efficient

Fuel efficient with 17.5 km/L

### Running Lights

This car has a Running lights

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

### Bluetooth

Enjoy your drive with bluetooth

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 107520 | Specs | Yes |
| Engine | 1.4L | Option Type | Basic |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | HATCHBACK | Fuel Efficiency | 17.5 km/L mileage |
| Wheel Type | Steel Wheels | Exterior Color | Exterior Color Black |
| Interior Trim | Fabric Trim | Number of Airbags | 2 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 1 Keys |
| VIN number | KL1CD6CA1LC477619 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|---|---|
| **Exteriors** | | | |
| Running Lights | ✓ | Halogen Headlights | ✓ |
| **Safety & Security** | | | |
| Traction Control | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |

| Comfort & Convenience | | | |
|---|---|---|---|
| Steering Mounted Audio Controls | ✓ | Rear Defogger | ✓ |
| Steering Column Adjuster | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | USB player | ✓ |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

### Doors condition

| | |
|---|---|
| Front left door<br>Handle: Color Dullness | Front right door<br>Handle: Discoloured, Light Scuffing < 50mm |
| Rear left door | Rear right door<br>Panel: Low Visual Dent < 30mm |

### Fenders Condition

| | |
|---|---|
| Left Fender<br>Condition: Light Scuffing | Right Fender<br>Right Fender: Light Scuffing |

### Quarter Panels Condition

| | |
|---|---|
| Left Quarter Panel | Right Quarter Panel<br>Condition: Light Scuffing |

### Front Bumper Condition

Front Bumper

### Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm

### Hood Condition

Hood
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm

### Trunk Condition

Trunk

### Trunk conditon

Trunk

### Pillars Condition

| | |
|---|---|
| Left A Pillar | Right A Pillar |
| Left A to B Pillar Beading | Right A to B Pillar Beading |

| | | | |
|---|---|---|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |

Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |

Cowl Top

| | |
|---|---|
| Cowl Top | ✓ |

Rear View Mirror Condition

| | | | |
|---|---|---|---|
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |

Alloy Wheel/ Rim

| | | | |
|---|---|---|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |

| | | | |
|---|---|---|---|
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |

Panel Condition

| | |
|---|---|
| Rear Trunk Panel | ✓ |

## Engine & Transmission

Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |

Fuel System

| | | | |
|---|---|---|---|
| Fuel Tank | ✓ | | |

Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

## Steering, Suspension & Brakes

Steering

| | | | |
|---|---|---|---|
| Steering wheel | ✓ | | |

Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |

Suspension

| | | | |
|---|---|---|---|
| Shock Absorbers | ✓ | | |

## Electricals, Controls & Lights

Keys

| | | | |
|---|---|---|---|
| Master Key | ✓ | Spare Key(s) | ✓ |

Door Locks

| | | | |
|---|---|---|---|
| Child Safety Locking | ✓ | | |

Dashboard

| | | | |
|---|---|---|---|
| Instrument Panel | ✓ | | |

Airbags

| | | | |
|---|---|---|---|
| Airbags | ✓ | | |

| | | | |
|---|---|---|---|
| Controls | ✓ | Cruise Control | ✓ |

| | | | |
|---|---|---|---|
| Heads Up Display | ✓ | Infotainment Display | ✓ |
| OBD Connector | ✓ | Music System | ✓ |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | License Plate Light | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Glove Box | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ✓ |
| Grab Handle | ✓ | Carpet | ✓ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

## Tyres

| | | | |
|---|---|---|---|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |

| | | | |
|---|---|---|---|
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <85% |
| Spare Tyre | <55% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE