



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 JEEP GRAND CHEROKEE

LIMITED | 103,357 KM

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play















Enjoy your drive with apple play



Amazing Comfort












Power driver seat, Memory Seats & more





Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 103357 |  Specs | Yes |
|  Engine | 3.6L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 8.6 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Leather Trim |  Number of Airbags | 7 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | 1C4RJFBG3MC602977 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-----------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Memory Seats |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls |  | Power Folding Mirrors |  |
| Ventilated Seat |  | Power Tailgate/ Power Trunk |  |
| Rear Defogger |  | Central Armrest |  |

| | | | |
|--|---|-----------------------|---|
| Remote Engine Start | ✓ | Automatic Headlights | ✓ |
| Steering Column Adjuster | ✓ | | |
|  Exteriors | | | |
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |
| HID Headlights | ✓ | | |
|  Safety & Security | | | |
| Navigation | ✓ | Parking Sensors Front | ✓ |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Blind Spot Monitor | ✓ | Traction Control | ✓ |
| Airbag Curtain Shield | ✓ | Airbag Knees | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Performance | | | |
| Paddle Shift | ✓ | Hill Descent Control | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | USB Charging Port | ✓ |
| Infotainment System | ✓ | USB player | ✓ |





150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|---|---|
| Front left door |  | Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Scuffing > 50mm |  |
| Rear left door |  | Rear right door Panel: Light Scuffing < 50mm |  |

Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender Condition: Low Visual Dent, Light Scuffing |  | Right Fender Right Fender: Low Visual Dent, Light Scuffing |  |
|---|---|---|---|


Quarter Panels Condition

| | | | |
|--------------------|---|--|---|
| Left Quarter Panel |  | Right Quarter Panel Condition: Light Scuffing |  |
|--------------------|---|--|---|


Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper Rear Bumper: Light Scuffing < 80mm |  |
|---|---|

Hood Condition

| | |
|---------------------------------------|---|
| Hood Bonnet: Light Scuffing < 50mm |  |
|---------------------------------------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|--|---|------------------------------|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | | | |
| Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition | ! |
| | | Light Scuffing < 50mm | |

| | | | |
|------------------|---|--------------|---|
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

| | | | |
|--------------------------------|---|-------------------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Gear shift | ✓ |
| Drive Axle | ✓ | 4*4 Condition (If Applicable) | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

















Electricals, Controls & Lights

| | | | |
|------------|---|--------------|---|
| Keys | | | |
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |

| | | | |
|-----------------------|---|-------------------------|---|
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Radar (If Equipped) | ✓ | Navigation System | ✓ |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | Seat Heaters | ✓ |
| Memory Seats | ✓ | | |



Interiors & Luggage

| | | | |
|--|---|----------------------|---|
| Dashboard And Instrument Panel |  | Central Console |  |
| Cup Holder |  | Glove Box |  |
| Steering Wheel Color Faded |  | Sunvisor |  |
| Seat Upholstery Driver Seat: Minor Smudge/ Cracks |  | Manual Seat Movement |  |
| Seat Belts |  | Head Rest |  |
| Door Controls And Trim Front Left Door: Fair Use Wear |  | Grab Handle |  |
| Carpet |  | Headliner |  |
| Rear View Mirror |  | Toolkit |  |

Tyres

Tyres Condition

| | | | |
|----------------------------|---|---------------------------|---|
| Left Hand Side Front Tyre |  | Left Hand Side Rear Tyre |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre |  | | |
| Life remaining | | | |
| LHS Front Tyre | <85% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <65% |
| Spare Tyre | <85% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE