



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 TOYOTA RAV4

ADVENTURE | 39,534 KM

VIN: JTMJ13FVXMD082131

Car highlights



Manufacturer warranty

Till 30/10/2026 (Not verified)



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play















Enjoy your drive with apple play



Amazing Comfort












Power driver seat

Basic Details

 Kilometers	39534	 Specs	Yes
 Engine	2.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	14.2 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	9 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JTMJ13FVXMD082131		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Power Tailgate/ Power Trunk	
Rear Defogger		Central Armrest	
Automatic Headlights		Steering Column Adjuster	



Exteriors

Fog Light Front



Roof Rails



Running Lights



Rear Bumper Spoiler



LED Headlights



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Knees



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Performance

Hill Descent Control



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



USB Charging Port



Infotainment System



USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Low Visibility Dent < 30mm	
Rear left door		Rear right door	
Panel: Colour faded		Panel: Low Visual Dent < 30mm, Paint Defect, Colour Mismatch/ Low Brightness	

Fenders Condition

Left Fender		Right Fender	
		Right Fender: Light Scuffing	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Colour faded			

Front Bumper Condition

Front Bumper	
Moulding: Misaligned/ Not Properly Fixed	

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
Bonnet: Paint Damage/ Low Brightness	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
Roof Moulding Condition: Minor Rubber Beading Fair Use Wear	

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓

Wiper	✓	
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Condition	✓	Radiator Coolant ✓
Fuel System		
Fuel Tank	✓	
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓
Transmission Fluid	✓	

Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Disc & Brake Pad	✓	Brake Fluid ✓
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys	
Master Key	✓
Door Locks	
Child Safety Locking	✓
Dashboard	

Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓

Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE