



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 VOLKSWAGEN TERAMONT

TRENDLINE | 93,129 KM

VIN: WVGAD1CA5NC563775

Car highlights



Boosted Engine

This car has a Boosted Engine



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play
















Enjoy your drive with apple play



Amazing Comfort










Power driver seat



Basic Details

| | | | |
|--|-------------------|---|---------------------|
|  Kilometers | 93129 |  Specs | Yes |
|  Engine | 2.0L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Blue |
|  Interior Trim | Fabric Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 7 Seats |  Number of keys | 2 Keys |
|  VIN number | WVGAD1CA5NC563775 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Cruise Control |  | Steering Mounted Audio Controls |  |
| Rear Defogger |  | Central Armrest |  |
| Steering Column Adjuster |  | | |
|  Exteriors | | | |
| Roof Rails |  | Running Lights |  |

| | | |
|--|---|-------------------------|
| LED Headlights | ✓ | |
|  Safety & Security | | |
| Reverse Camera | ✓ | Blind Spot Monitor ✓ |
| Traction Control | ✓ | Airbag Curtain Shield ✓ |
| Airbag Driver Front | ✓ | ABS ✓ |
| Central Locking | ✓ | Child Safety Locking ✓ |
|  Entertainment | | |
| Bluetooth Player | ✓ | Apple Play ✓ |
| Android Auto Play | ✓ | USB Charging Port ✓ |
| Infotainment System | ✓ | USB player ✓ |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior



Doors condition

| | | | |
|---------------------|---|--|---|
| Front left door |  | Front right door | |
| | | Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm |  |
| Rear left door | | Rear right door | |
| Panel: Colour faded |  | Panel: Acid Marks/ Bird Dropping < 5mm |  |

Fenders Condition

| | | | |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|


Quarter Panels Condition

| | | | |
|--------------------|---|---|---|
| Left Quarter Panel |  | Right Quarter Panel | |
| | | Condition: Low Visual Dent, Acid Marks/ Bird Dropping |  |

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |

Hood Condition

| | |
|---|---|
| Hood | |
| Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm |  |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | | | |
|-----------------------------|---|------------------------------|---|
| Roof | ✓ | | |
| Pillars Condition | | | |
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ! | Monogram | ✓ |
| Light Scuffing < 50mm | | | |

Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key

Button Faded



Spare Key(s)



Door Locks

Child Safety Locking



| | | | |
|----------------------|---|--|---|
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Radar (If Equipped) | ✓ | Music System | ✓ |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | |
| License Plate Light | ✓ | Right DRL: Low Brightness, Lamps Are Not Working | ! |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |

| | | | |
|------------------------|---|-------------|---|
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|------|---------------------------|------|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <65% |
| Spare Tyre | <45% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE