



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 JEEP COMPASS LONGITUDE | 92,110 KM

VIN: 3C4NJDBB2KT811927

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details

Yes	Specs	GCC	92110	Kilometers	
Semi Loaded	Option Type	*	2.4L	Engine	
Four Wheel Drive	Drive	1- <mark>0</mark> -1 1-11-1	Automatic	Transmission	ARRO
12.2 km/L mileage	Fuel Efficiency		SUV	Body Type	
Exterior Color Grey	Exterior Color		Alloy Wheels	Wheel Type	
6 Airbags	Number of Airbags	100	Fabric Trim	Interior Trim	*
2 Keys	Number of keys	E	5 Seats	Seating Capacity	Ä
			3C4NJDBB2KT811927	VIN number	000

Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Exteriors Exteriors			
Fog Light Front	~	Roof Rails	•
Running Lights	~	Rear Bumper Spoiler	•
Halogen Headlights	✓		
Performance			
Differential Locks	✓		
Safety & Security			
Traction Control	•	Airbag Curtain Shield	✓
Airbag Driver Front	~	ABS	•
Central Locking	~	Child Safety Locking	•
্ৰে Entertainment			
Bluetooth Player	•	USB Charging Port	✓
Infotainment System		USB player	


150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Low Visual Dent < 50mm	(!)
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	(!)	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission Engine Engine Body **Engine Performance** Engine Oil (Condition & Level) **Exhaust System** Turbocharger/ Supercharger **Radiator Condition Radiator Coolant** Fuel System Fuel Tank **Transmission Operation** Gear Shifting Drive Axle 4*4 Condition (If Applicable) Transmission Fluid Steering, Suspension & Brakes Steering Steering wheel Brake System Parking Brake Brake Master Cylinder Brake Fluid Brake Disc & Brake Pad Suspension **Shock Absorbers Electricals, Controls & Lights** Keys Master Key Spare Key(s) Door Locks Child Safety Locking Dashboard Instrument Panel Dash Light Operation: Not Working Airbags



Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Life remaining LHS Front Tyre <75% LHS Rear Tyre <75% RHS Front Tyre <75% RHS Rear Tyre <85% Spare Tyre <85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE