



### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2022 NISSAN X TRAIL S | 118,602 KM

VIN: JN1BT2MU1NW025747

## **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



#### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



| Rear Bumper Spoiler | <b>✓</b> | Halogen Headlights   | <b>✓</b> |
|---------------------|----------|----------------------|----------|
| Safety & Security   |          |                      |          |
| Reverse Camera      | <b>v</b> | Traction Control     | <b>✓</b> |
| Airbag Driver Front | <b>✓</b> | ABS                  | V        |
| Central Locking     | <b>✓</b> | Child Safety Locking | <b>✓</b> |
| 🕼 Entertainment     |          |                      |          |
| Bluetooth Player    | <b>✓</b> | Infotainment System  | <b>✓</b> |
| USB player          | <b>~</b> |                      |          |

## **150 Point Detailed Inspection Report**


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



| Left A Pillar               | •        | Right A Pillar Inner Condition: Light Scuffing | (!)      |
|-----------------------------|----------|--|----------|
| Left A to B Pillar Beading  | <b>✓</b> | Right A to B Pillar Beading                    | <b>✓</b> |
| Right A to B Pillar         | <b>✓</b> | Left B Pillar                                  | <b>✓</b> |
| Left B Pillar Trim          | <b>✓</b> | Left B to C Pillar Beading                     | <b>✓</b> |
| Right C Pillar Trim         | <b>✓</b> | Right B to C Pillar                            | <b>✓</b> |
| Right B to C Pillar Beading | <b>✓</b> | Left C Pillar                                  | <b>✓</b> |
| Running Board Condition     |          |  |          |
| Left Running Board          | <b>✓</b> | Right Running Board                            | <b>✓</b> |
| Windshield Condition        |          |  |          |
| Front Windshield            | <b>✓</b> | Rear Windshield                                | <b>✓</b> |
| Structural Assessment       |          |  |          |
| Chassis Condition           | <b>✓</b> | Apron  | <b>✓</b> |
| Boot Floor                  | <b>✓</b> | Firewall Condition                             | <b>✓</b> |
| Cowl Top                    | <b>✓</b> | Head Light Support Condition                   | •        |
| Cowl Top                    |          |  |          |
| Cowl Top                    | <b>✓</b> |  |          |
| Rear View Mirror Condition  |          |  |          |
| Left Hand Side Mirror       | <b>✓</b> | Left Side Mirror                               | <b>✓</b> |
| Right Side Mirror           | <b>✓</b> |  |          |
| Alloy Wheel/ Rim            |          |  |          |
| Left Front Alloy/ Rim       | <b>✓</b> | Left Rear Alloy/ Rim                           | <b>✓</b> |
| Right Front Alloy/ Rim      | <b>✓</b> | Right Rear Alloy/ Rim                          | <b>✓</b> |
| Spare Alloy/ Rim Condition  | <b>✓</b> |  |          |
| Wheel cover                 | <b>✓</b> | Antenna  | •        |
| Grill Condition             | (!)      | Monogram                                       |          |
| Light Scuffing < 50mm       | $\odot$  | Monogram                                       | •        |
| Window Glass                | <b>✓</b> | Wiper  | <b>✓</b> |
|                             |          |  |          |

| Panel Condition                |          |                       |          |
|--------------------------------|----------|-----------------------|----------|
| Rear Trunk Panel               | <b>✓</b> |                       |          |
|                                |          |                       |          |
| Engine                         |          |                       |          |
| Engine Body                    | <b>✓</b> | Engine Performance    | <b>✓</b> |
| Engine Oil (Condition & Level) | <b>✓</b> | Exhaust System        | <b>✓</b> |
| Radiator Condition             | <b>✓</b> | Radiator Coolant      | <b>✓</b> |
| Fuel System                    |          |                       |          |
| Fuel Tank                      | <b>✓</b> |                       |          |
| Transmission Operation         |          |                       |          |
| Gear Shifting                  | <b>✓</b> | Drive Axle            | <b>✓</b> |
| Transmission Fluid             | <b>✓</b> |                       |          |
| Steering, Suspension & Brakes  |          |                       |          |
| Steering                       |          |                       |          |
| Steering wheel                 | <b>✓</b> |                       |          |
| Brake System                   |          |                       |          |
| Parking Brake                  | <b>✓</b> | Brake Master Cylinder | <b>✓</b> |
| Brake Disc & Brake Pad         | <b>✓</b> | Brake Fluid           | <b>✓</b> |
| Suspension                     |          |                       |          |
| Shock Absorbers                | <b>✓</b> |                       |          |
| Electricals, Controls & Lights |          |                       |          |
| Keys                           |          |                       |          |
| Master Key                     | <b>✓</b> | Spare Key(s)          | <b>✓</b> |
| Door Locks                     |          |                       |          |
| Child Safety Locking           | <b>✓</b> |                       |          |
| Dashboard                      |          |                       |          |
| Instrument Panel               | <b>✓</b> |                       |          |
| Airbags                        |          |                       |          |

| Airbags   | <b>✓</b>  |   |  |
|---|---|---|--|
| Controls  | <b>✓</b>  | Cruise Control  | <b>✓</b>   |
| Infotainment Display  | <b>✓</b>  | OBD Connector   | <b>✓</b>   |
| Music System  | <b>✓</b>  | Camera  | •  |
| Lights  |   |   |  |
| Headlight   | <b>✓</b>  | Interior Lights   | <b>✓</b>   |
| Tail Light Cluster  | <b>✓</b>  | Daylight Running Lights   | <b>✓</b>   |
| License Plate Light   | <b>✓</b>  |   |  |
| Air Conditioning  |   |   |  |
| AC Cooling  | <b>✓</b>  | AC Switch   | <b>✓</b>   |
| AC System Leaks   | <b>✓</b>  | Center AC Vent  | <b>✓</b>   |
| Front Right AC Vent   | <b>✓</b>  | Heater  | <b>✓</b>   |
| Rear Blower Switch  | <b>✓</b>  |   |  |
|   |   |   |  |
| Rear Defogger   | <b>✓</b>  | USB Charging Port   | <b>✓</b>   |
| Rear Defogger Power/ Manual Windows   | <b>✓</b>  | USB Charging Port   | <b>✓</b>   |
|   | <b>⋄</b>  | USB Charging Port   | •  |
| Power/ Manual Windows   | <ul><li></li><li></li><li></li></ul>  | USB Charging Port  Central Console                                    | <b>✓</b>   |
| Power/ Manual Windows  Interiors & Luggage  | <ul><li></li><li></li><li></li><li></li><!--</td--><td></td><td>✓</td></ul> |   | ✓  |
| Power/ Manual Windows  Interiors & Luggage  Dashboard And Instrument Panel  | <ul><li>*</li><li>*</li><li>*</li><li>*</li></ul>                           | Central Console   | •  |
| Power/ Manual Windows  Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  |   | Central Console Glove Box   | <ul> <li>*</li> <li>*</li> <li>*</li> <li>*</li> </ul> |
| Power/ Manual Windows  Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  |   | Central Console  Glove Box  Sunvisor                                  |  |
| Power/ Manual Windows  Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery                                     |   | Central Console  Glove Box  Sunvisor  Manual Seat Movement            |  |
| Power/ Manual Windows  Interiors & Luggage  Dashboard And Instrument Panel  Cup Holder  Steering Wheel  Seat Upholstery  Seat Belts  Door Controls And Trim |   | Central Console  Glove Box  Sunvisor  Manual Seat Movement  Head Rest |  |





# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE