

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 FORD ESCAPE

SE | 103,144 KM

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Great Parking Assistance

Reverse Camera

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	103144	Specs	Yes
Engine	2.5L	Option Type	Semi Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SUV	Fuel Efficiency	11.9 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color White
Interior Trim	Leather Trim	Number of Airbags	7 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	WF0BM4AFXJVL48736		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Steering Mounted Audio Controls	✓	Rear Defogger	✓
Central Armrest	✓	Steering Column Adjuster	✓
Exteriors			
Fog Light Front	✓	Halogen Headlights	✓

Performance			
Paddle Shift	✓		
Safety & Security			
Reverse Camera	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Knees	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front left door

Front right door
Panel: Light Scuffing < 50mm, Low Visibility
Dent < 30mm, Paint Chip-off < 5mm

Rear left door

Rear right door
Panel: Light Scuffing < 50mm, Low Visual
Dent < 30mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender
Condition: Light Scuffing, Low Visual Dent, Paint Chip-off

Right Fender
Right Fender: Light Scuffing

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel
Condition: Light Scuffing, Low Visual Dent

Front Bumper Condition

Front Bumper

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm

Trunk Condition

Trunk

Trunk conditon

Trunk

Roof Condition

Roof	✓		

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield Beading: Mouldings Crack/ Fair Use Wear < 50mm	!	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓

Cowl Top

Cowl Top Fair Use Wear/Crack<5mm	!

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel cover	✓	Antenna	✓

Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			

Child Safety Locking

Dashboard

Instrument Panel

Airbags

Airbags

Controls

Cruise Control

Infotainment Display

OBD Connector

Music System
Condition: Knob Fair Use Wear

Camera
Reverse Camera: Lens Damaged/ Blurred

Lights

Headlight
Left: Light Scuff Marks < 50mm

Interior Lights

Tail Light Cluster

Daylight Running Lights

License Plate Light

Fog Lights

Air Conditioning

AC Cooling

AC Switch

AC System Leaks

Center AC Vent

Front Right AC Vent

Heater

Rear Blower Switch
Fair Use Wear

Rear Defogger

USB Charging Port

Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted, Minor Color Dullness

Central Console
Gear Shift Knob: Knob Fair Use Wear

Glove Box

Steering Wheel
Steering Wheel Fair Use Wear

Sunvisor

Seat Upholstery

Driver Seat: Minor Smudge/ Cracks

Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE