



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 TOYOTA YARIS

SE | 99,250 KM

VIN: MHFB29F36M2147723

Car highlights

Fuel Efficient

Fuel efficient with 18.8 km/L



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	99250	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel Efficiency	18.8 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	MHFB29F36M2147723		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 Safety & Security			
Traction Control		Airbag Driver Front	
ABS		Central Locking	

Child Safety Locking



Entertainment

Bluetooth Player



USB player



Exteriors

Halogen Headlights



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Low Visibility Dent < 30mm

Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Right Fender: Low Visual Dent, Light Scuffing

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent, Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Paint Faded

Hood Condition

Hood



Bonnet: Paint Damage/ Low Brightness

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition			
Wheel cover		Antenna	
Grill Condition			
Colour Faded		Monogram	
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel			

Engine & Transmission

Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

Fuel System

Fuel Tank 

Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Suspension

Shock Absorbers 

Electricals, Controls & Lights

Keys

Master Key  Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	!	Interior Lights	✓
Right: Low Brightness Lamps			
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel		
Dashboard Upholstery: Minor Scuffing/ Disfigurement/ Melted	!	Central Console
Glove Box	✓	Steering Wheel
		Steering Wheel Fair Use Wear
Sunvisor	✓	Seat Upholstery
Manual Seat Movement	✓	Seat Belts
Head Rest	✓	Door Controls And Trim
Grab Handle	✓	Carpet
		Front Left Floor Mat: Smudge/Burn/Crack
Headliner	✓	Rear View Mirror
Toolkit	✓	

 **Tyres**

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<65%

RHS Front Tyre

<75%

RHS Rear Tyre

<55%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE