

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 SUZUKI CIAZ

GLX | 99,038 KM

VIN: MA3VC7A16PA459385

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	99038	Specs	Yes
Engine	1.5L	Option Type	Fully Loaded
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel	Petrol
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Silver
Interior Trim	Leather Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MA3VC7A16PA459385		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Rear Armrest with cupholder	✓	Steering Mounted Audio Controls	✓
Power Folding Mirrors	✓	Rear Defogger	✓
Central Armrest	✓	Automatic Headlights	✓
Steering Column Adjuster	✓		

Exteriors			
Fog Light Front	✓	Running Lights	✓
LED Headlights	✓		
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
Entertainment			
Bluetooth Player	✓	Infotainment System	✓

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front left door	Front right door Panel: Low Visibility Dent < 30mm, Paint Chip-off < 5mm, Light Scuffing < 50mm
Rear left door	Rear right door Panel: Scuffing > 50mm, Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender	Right Fender

Quarter Panels Condition

Left Quarter Panel	Right Quarter Panel

Front Bumper Condition

Front Bumper

Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm

Hood Condition

Hood

Bonnet: Dent > 30mm, Light Scuffing < 50mm

Trunk Condition

Trunk

Trunk conditon

Trunk

Roof Condition

Roof

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓

Windshield Condition

Front Windshield	✓	Rear Windshield Light Scuffing < 50mm	!

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓

Cowl Top

Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	!	Monogram	✓

Window Glass	✓	Wiper	✓

Panel Condition

Rear Trunk Panel	✓

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Fuel System

Fuel Tank	✓

Transmission Operation

Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering

Steering wheel	✓

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Suspension

Shock Absorbers	✓

Electricals, Controls & Lights

Keys

Master Key Button Faded	!	Spare Key(s)	✓

Door Locks

Child Safety Locking	✓

Dashboard

Instrument Panel

Airbags

Airbags

Controls

Cruise Control

Infotainment Display

Infotainment Display: Damaged Display, Display Low Brightness

OBD Connector

Music System

Camera

Lights

Headlight

Left: Light Scuff Marks < 50mm

Interior Lights

Tail Light Cluster

Daylight Running Lights

License Plate Light

Fog Lights

Right Fog Light: Light Scuff Marks < 50mm

Air Conditioning

AC Cooling

AC Switch

AC System Leaks

Center AC Vent

Front Right AC Vent

Crack/Fair Use Wear

Heater

Rear Blower Switch

Parking Sensors

Rear Defogger

USB Charging Port

Rear: Dummy Cap Missing

Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel

Central Console

Box: Minor Disfiguration, Minor Crack/Fair Use Wear/ Scuffing

Cup Holder

Glove Box

Steering Wheel

Sunvisor

Seat Upholstery Driver Seat: Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Rear Left Door: Crack/Fair Use Wear	!	Grab Handle	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner Front Left: Crack/Fair Use Wear, Light Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<85%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE