



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 MAZDA 6

S | 55,652 KM

VIN: JM7GL4S32N1471398

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	55652	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	12.8 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JM7GL4S32N1471398		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 Safety & Security			

Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Exteriors			
Running Lights	✓	LED Headlights	✓
 Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door		Rear right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	

Fenders Condition

Left Fender Condition: Light Scuffing, Low Visual Dent		Right Fender	
---	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Light Scuffing	
--------------------	---	--	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Dent < 50mm, Light Scuffing < 80mm	

Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel cover



Antenna



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System		Camera	!
Steering Mounted Audio Controls: Not Working Properly	!	Reverse Camera: Lens Damaged/ Blurred	!
Lights			
Headlight		Interior Lights	✓
Left: Scuff Marks > 50mm	!		
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	✓
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!		
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓

Carpet	✓	Headliner	✓
Rear View Mirror	!	Toolkit	✓
De Silvered Mirror<10%			

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<85%	LHS Rear Tyre	<65%
RHS Front Tyre	<85%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE