


**Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

**3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

**Car has been Refurbished**

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2024 MG RX5**

**LUXURY | 41,252 KM**

VIN: LSJA24U9XRS023171

## Car highlights

### Manufacturer warranty

Till 04/01/2030 (Not verified)

### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

### Apple play

Enjoy your drive with apple play

### Amazing Comfort

Power driver seat

## Basic Details

| | | | |
|---|---|---|---|
| Kilometers | 41252 | Specs | Yes |
| Engine | 1.5L | Option Type | Semi Loaded |
| Transmission | Automatic | Drive | Front Wheel Drive |
| Body Type | SUV | Fuel Efficiency | 12.8 km/L mileage |
| Wheel Type | Alloy Wheels | Exterior Color | Exterior Color Black |
| Interior Trim | Leather Trim | Number of Airbags | 6 Airbags |
| Seating Capacity | 5 Seats | Number of keys | 2 Keys |
| VIN number | LSJA24U9XRS023171 | | |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Safety & Security | | | |
|---|---|---|---|
| 360 degree Camera | ✓ | Navigation | ✓ |
| Parking Sensors Front | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera | ✓ | Traction Control | ✓ |
| Front Camera | ✓ | Side Camera | ✓ |
| Airbag Curtain Shield | ✓ | Airbag Driver Front | ✓ |

| | | | |
|---|---|---|---|
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
| **Comfort & Convenience** | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Rear Armrest with cupholder | ✓ | Steering Mounted Audio Controls | ✓ |
| Power Folding Mirrors | ✓ | Power Tailgate/ Power Trunk | ✓ |
| Rear Defogger | ✓ | Central Armrest | ✓ |
| Automatic Headlights | ✓ | Steering Column Adjuster | ✓ |
| **Exteriors** | | | |
| Roof Rails | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | LED Headlights | ✓ |
| **Performance** | | | |
| Hill Descent Control | ✓ | | |
| **Entertainment** | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | USB Charging Port | ✓ |
| Infotainment System | ✓ | USB player | ✓ |

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

**Passed**

## Exterior

Doors condition

| | | | |
|---|---|---|---|
| Front left door | ✓ | Front right door<br>Panel: Low Visibility Dent < 30mm | ! |
| Rear left door | ✓ | Rear right door<br>Panel: Low Visual Dent < 30mm | ! |

Fenders Condition

| | | | |
|---|---|---|---|
| Left Fender | ✓ | Right Fender | ✓ |

Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel | ✓ | Right Quarter Panel | ✓ |

Front Bumper Condition

| | |
|---|---|
| Front Bumper | ✓ |

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper<br>Rear Bumper: Scuffing > 80mm | ! |

Hood Condition

| | |
|---|---|
| Hood | ✓ |

Trunk Condition

| | |
|---|---|
| Trunk | ✓ |

Trunk conditon

| | |
|---|---|
| Trunk | ✓ |

Roof Condition

| | |
|---|---|
| Roof | ✓ |

Pillars Condition

| | | | |
|---|---|---|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |

| | | | |
|---|---|---|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |

Running Board Condition

| | | | |
|---|---|---|---|
| Left Running Board | ✓ | Right Running Board | ✓ |

Sunroof Glass Condition (If Equipped)

| | |
|---|---|
| Sun Roof Glass | ✓ |

Windshield Condition

| | | | |
|---|---|---|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |

Structural Assessment

| | | | |
|---|---|---|---|
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |

Cowl Top

| | |
|---|---|
| Cowl Top | ✓ |

Rear View Mirror Condition

| | | | |
|---|---|---|---|
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |

Alloy Wheel/ Rim

| | | | |
|---|---|---|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |

| | | | |
|---|---|---|---|
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram<br>Dent > 30mm | ! | Window Glass | ✓ |
| Wiper | ✓ | | |

Panel Condition

Rear Trunk Panel ✓

## Engine & Transmission

### Engine

| | | | |
|---|---|---|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |

### Fuel System

| | | | |
|---|---|---|---|
| Fuel Tank | ✓ | | |

### Transmission Operation

| | | | |
|---|---|---|---|
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

## Steering, Suspension & Brakes

### Steering

| | | | |
|---|---|---|---|
| Steering wheel | ✓ | | |

### Brake System

| | | | |
|---|---|---|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |

### Suspension

| | | | |
|---|---|---|---|
| Shock Absorbers | ✓ | | |

## Electricals, Controls & Lights

### Keys

| | | | |
|---|---|---|---|
| Master Key | ✓ | | |

### Door Locks

| | | | |
|---|---|---|---|
| Child Safety Locking | ✓ | | |

### Dashboard

| | | | |
|---|---|---|---|
| Instrument Panel | ✓ | | |

Airbags

| | | | |
|---|---|---|---|
| Airbags | ✓ | | |

| | | | |
|---|---|---|---|
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Navigation System | ✓ | Music System | ✓ |

Sunroof Operation

| | | | |
|---|---|---|---|
| Sunroof | ✓ | | |

Lights

| | | | |
|---|---|---|---|
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | | |

Air Conditioning

| | | | |
|---|---|---|---|
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

| | | | |
|---|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |

| | | | |
|---|---|---|---|
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

## Tyres

Tyres Condition

| | | | |
|---|---|---|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Life remaining

| | | | |
|---|---|---|---|
| LHS Front Tyre | <55% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <45% | RHS Rear Tyre | <55% |
| Spare Tyre | <65% | | |




## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE