



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 MINI COOPER

S | 35,143 KM

VIN: WMW51DH0XP2T32232

Car highlights

Service History

Service history available



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play















Enjoy your drive with apple play



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	35143	 Specs	Yes
 Engine	2.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	Fuel Efficiency	16.1 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Other
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	4 Seats	 Number of keys	1 Keys
 VIN number	WMW51DH0XP2T32232		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Heads up Display		Climate Control AC	
Cruise Control		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Automatic Headlights	
Steering Column Adjuster			



Safety & Security

Lane Departure Warning
System



Navigation



Parking Sensors Front



Parking Sensors Rear



Auto Park Assist



Reverse Camera



Collision Warning System



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Performance

Paddle Shift



Exteriors

Running Lights



Rear Bumper Spoiler



LED Headlights



Entertainment

Bluetooth Player



Apple Play



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar		Left B Pillar	
---------------------	---	---------------	---

Left B Pillar Trim		Right C Pillar Trim	
--------------------	---	---------------------	---

Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Antenna



Grill Condition



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Cruise Control	✓	Heads Up Display	✓
Infotainment Display	✓	OBD Connector	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System			
Steering Mounted Audio Controls: Button(s)	!		

Faded

Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner







Rear View Mirror



Toolkit



Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE