



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2019 RENAULT DUSTER PE | 85,098 KM

VIN: VF1HSRMX8KA467994

# **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



## **Great Parking Assistance**

Reverse Camera

## **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



#### **Bluetooth**


Enjoy your drive with bluetooth



## **Amazing Comfort**


Power driver seat

#### **Basic Details**



# **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Rear Defogger	<b>✓</b>	Steering Column Adjuster	•
🖔 Safety & Security			
Reverse Camera	<b>✓</b>	Airbag Driver Front	<b>✓</b>
ABS	<b>✓</b>	Central Locking	<b>✓</b>
Child Safety Locking	<b>✓</b>		
្សែ Entertainment			
Bluetooth Player	<b>✓</b>	Infotainment System	<b>✓</b>
USB player	<b>✓</b>		

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left B Pillar Trim  Left B to C Pillar Beading  Right C Pillar Trim  Right B to C Pillar	
Right C Pillar Trim Right B to C Pillar	
Right B to C Pillar Beading  Left C Pillar	
Running Board Condition	
Left Running Board Right Running Board	
Windshield Condition	
Front Windshield Rear Windshield	
Structural Assessment	
Chassis Condition	
Boot Floor Firewall Condition	
Cowl Top Head Light Support Condition	
Cowl Top	
Cowl Top	
Rear View Mirror Condition	
Left Hand Side Mirror  Left Side Mirror	
Right Side Mirror	
Alloy Wheel/ Rim	
Left Front Alloy/ Rim ✓ Left Rear Alloy/ Rim	
Right Front Alloy/ Rim Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition	
Wheel cover Antenna	
Grill Condition   Monogram	
Window Glass Wiper	
Panel Condition	
Rear Trunk Panel	

Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>
Transmission Fluid	<b>✓</b>		
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	•
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>	Spare Key(s)	•
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	~		
Airbags			
Airbags	<b>✓</b>		
Controls	<b>✓</b>	Cruise Control	<b>✓</b>

Infotainment Display	<b>✓</b>	OBD Connector	<b>~</b>
Music System Steering Mounted Audio Controls: Not Working Properly	(!)	Camera	•
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Daylight Running Lights Right DRL: Low Brightness	(!)
License Plate Light	<b>✓</b>	Fog Lights	<b>✓</b>
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent Fair Use Wear	(!)	Heater	•
Rear Defogger	<b>✓</b>	USB Charging Port	<b>✓</b>
Power/ Manual Windows	<b>✓</b>		
Power/ Manual Windows  Interiors & Luggage	•		
	•	Central Console  Gear Shift Knob: Knob Fair Use Wear	<u>(1)</u>
Interiors & Luggage	<ul><li></li><li></li><li></li></ul>		① •
Interiors & Luggage  Dashboard And Instrument Panel		Gear Shift Knob: Knob Fair Use Wear	<ul><li>!</li><li>✓</li></ul>
Interiors & Luggage  Dashboard And Instrument Panel  Glove Box	<ul><li>*</li><li>*</li><li>*</li><li>*</li></ul>	Gear Shift Knob: Knob Fair Use Wear  Steering Wheel	
Interiors & Luggage  Dashboard And Instrument Panel  Glove Box  Sunvisor		Gear Shift Knob: Knob Fair Use Wear  Steering Wheel  Seat Upholstery	
Interiors & Luggage  Dashboard And Instrument Panel  Glove Box  Sunvisor  Manual Seat Movement	<ul><li>&gt;</li><li>&gt;</li><li>&gt;</li><li>&gt;</li></ul>	Gear Shift Knob: Knob Fair Use Wear  Steering Wheel  Seat Upholstery  Seat Belts	
Interiors & Luggage  Dashboard And Instrument Panel  Glove Box  Sunvisor  Manual Seat Movement  Head Rest		Gear Shift Knob: Knob Fair Use Wear  Steering Wheel  Seat Upholstery  Seat Belts  Door Controls And Trim	

### Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Life remaining LHS Front Tyre <65% LHS Rear Tyre <75% RHS Front Tyre <65% RHS Rear Tyre <75% Spare Tyre <65%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE