



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2024 MG GT

STD | 53,832 KM

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	53832	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	LSJA36U38RN059069		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Automatic Headlights		Steering Column Adjuster	
 Safety & Security			
Parking Sensors Rear		Reverse Camera	

Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Exteriors			
Running Lights		LED Headlights	
 Entertainment			
Bluetooth Player		Apple Play	
Android Auto Play		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Dent > 50mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip			
Mark<5mm, Passenger Side/Stone Chip	!	Rear Windshield	✓
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags			
Controls		Cruise Control	
Infotainment Display		OBD Connector	
Music System		Camera	
Lights			
Headlight		Interior Lights	
Tail Light Cluster		Daylight Running Lights	
License Plate Light			
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch			
Parking Sensors		Rear Defogger	
USB Charging Port		Power/ Manual Windows	

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Glove Box		Steering Wheel	
Sunvisor		Seat Upholstery	
Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
Grab Handle		Carpet	
Headliner		Rear View Mirror	



Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE